

Site: PCB Treatment, Inc.  
SFO: PCBREF  
Doc Type: RPT  
Author: Dynamac

CERCLIS: MOD063670350  
Access: REL  
Recipient: EPA

Site ID: 07RK

# PCB Treatment, Inc.

## Review of facilities requiring follow-up and warning letters

January 21, 1997

2016301



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** 80 S. 8th Limited Partnership

**Other Name:**

**EPA Assigned ID #:** 10000

**Contact:** Paul Lucas

**Address:** 80 S. 8th 1920 IDS  
Minneapolis MN 55402

**Phone:**

**104(e) Response Comments:** Followup 104(e) was sent 6/21/96 to PO Box 391, Wilmington, DE 19899. No green card returned, no response received. Information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** 903 North Main Street Property

**Other Name:**

**EPA Assigned ID #:** 10025

**Contact:**

**Address:** 903 North Main St.  
Syracuse NY 13201-030

**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned FOE. No response received from facility. Information taken from PCB facility file. COD date is prior to date received at facility.

**Warning Letter Comments:**

**104(e) LETTER INFO**

**WARNING LETTER INFO**

**Date Sent to Facility**

8/ 4/95

**Date Received by Facility**

8/10/95

**Date Response Received by EPA**

**Date of Letter**

**Date Sent to Facility**

6/21/96

**Date Received by Facility**

6/24/96

**Date Response Received by EPA**

**Date of Letter**

*Response received 10/30/96, dated 10/25/96*

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	A & N Electric	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 9/95
EPA Assigned ID #:	11550	Date Response Received by EPA	9/11/95
		Date of Letter	9/ 5/95
Contact:	O. Donald Bowling		
Address:	Box 1128		
	Parksley VA 23421		
Phone:	804-665-5116		
104(e) Response Comments: Unable to locate facility file for HWM #1103.			
Warning Letter Comments:			
Facility:	A. Jones Community Center	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	11575	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	310 Kiamensi Road		
	Wilmington DE 19804		
Phone:			
104(e) Response Comments: No response received from facility. Information taken from PCB facility file.			
Warning Letter Comments:			
Facility:	A.O. Smith Corporation	Date Sent to Facility	8/ 4/95
Other Name:	(A.O. Smith Auto Products Co.)	Date Received by Facility	
EPA Assigned ID #:	11600	Date Response Received by EPA	9/18/95
		Date of Letter	9/15/95
Contact:	Kenneth L. Anselment, Jr.		
Address:	PO Box 23973		
	Milwaukee WI 53223-0973		
Phone:	414-359-4149		
104(e) Response Comments: Generator cannot locate any records regarding shipment of materials to PCB. Info taken from PCB facility file.			
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	(ACCO Babcock) FKI INDUSTRIES	Date Sent to Facility	6/21/96
Other Name:		Date Received by Facility	6/25/96
EPA Assigned ID #:	10125	Date Response Received by EPA	7/26/96
		Date of Letter	7/23/96
Contact:			
Address:	<del>12755 E. 9 Mile Road</del> Warren MI <del>48089</del>		
Phone:			
104(e) Response Comments:	8/4/95 letter returned FOE. Generator has no knowledge or information regarding shipments sent to PCB. Information taken from PCB facility file.		
Warning Letter Comments:			
Facility:	ALPO Pet Foods, Inc.	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	10525	Date Response Received by EPA	10/ 2/95
		Date of Letter	9/29/95
Contact:	Don Faas		
Address:	Mail Station 3726 Minneapolis MN 55402-1464		
Phone:	612-333-4800		
104(e) Response Comments:	The Pillsbury Company responded on behalf of ALPO Pet Products and Green Giant.		
Warning Letter Comments:			
Facility:	AM General	Date Sent to Facility	8/ 4/95
Other Name:	(Ren Acquisition)	Date Received by Facility	8/ 8/95
EPA Assigned ID #:	10600	Date Response Received by EPA	9/ 5/95
		Date of Letter	8/31/95
Contact:	T.R. MacDougall		
Address:	105 N. Niles Ave., Box 7025 South Bend IN 46634-7025		
Phone:	219-284-2915		
104(e) Response Comments:	Generator claims to have no knowledge of material sent to PCB. Info taken from facility file.		
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	ASCO Electric Company	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	11200	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	105 Vermont Street Odessa TX 79763		
Phone:			
104(e) Response Comments: 8/4/95 letter returned unclaimed. Information taken from PCB facility file.			
Warning Letter Comments:			
Facility:	Afton, City of	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	14375	Date Response Received by EPA	8/ 9/95
		Date of Letter	8/ 7/95
Contact:	Virginia Rawlings		
Address:	115 E. Kansas, PO Box 247 Afton IA 50830		
Phone:	515-347-5224		
104(e) Response Comments: To the best of their knowledge, the City of Afton did not use PCB facilities. Info taken from PCB facility file.			
Warning Letter Comments:			
Facility:	Allen Electric Company	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	5/21/96
EPA Assigned ID #:	10375	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	2101 North Main Box Helena MT 59601		
Phone:			
104(e) Response Comments:			
Warning Letter Comments: Warning letter returned refused - out of business. Information taken from PCB facility file.			

***PCB Treatment, Inc. General Information***  
***Review of Facilities Requiring Follow-up and Warning Letters***

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	AlliedSignal	Date Sent to Facility	8/ 4/95	
Other Name:	(Allied Corporation)	Date Received by Facility		
EPA Assigned ID #:	34875	Date Response Received by EPA	9/ 5/95	
		Date of Letter	9/ 1/95	
Contact:	Pamela Cissik			
Address:	PO Box 2245			
	Morristown NJ 07962-2245			
Phone:	210-455-5422			
104(e) Response Comments: Generator has no knowledge or documents pertaining to shipments sent to PCB. Information taken from PCB facility file.				
Warning Letter Comments:				
Facility:	Allis Chalmers Corporation	Date Sent to Facility	8/ 4/95	5/21/96
Other Name:		Date Received by Facility	8/ 8/95	5/24/96
EPA Assigned ID #:	10475	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	1126 South 70th St			
	West Allis WI 53214			
Phone:				
104(e) Response Comments:				
Warning Letter Comments: No response received. Information taken from PCB facility file.				
Facility:	Altus, City of	Date Sent to Facility	8/ 4/95	5/21/96
Other Name:	(Altus Electric Light Department)	Date Received by Facility	8/ 7/95	5/23/96
EPA Assigned ID #:	10550	Date Response Received by EPA		
		Date of Letter		6/21/96
Contact:	Jerry Carter			
Address:	221 Metric Lane			
	Altus OK 73521			
Phone:	405-481-2240			
104(e) Response Comments:				
Warning Letter Comments: Generator has no documents in their possession that predate 1985. Information taken from PCB facility file.				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Alumax Extrusions	Date Sent to Facility	6/21/96
Other Name:		Date Received by Facility	6/26/96
EPA Assigned ID #:	10575	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	2700 International Dr., #200		
	West Chicago IL 60185-1667		
Phone:			
104(e) Response Comments:	8/4/95 letter returned FOE. No response received from followup letter. Information taken from PCB facility file.		
Warning Letter Comments:			
Facility:	Amaco Plastics	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	10625	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	45 E. Maryland Ave.		
	St. Paul MN 55117		
Phone:			
104(e) Response Comments:	8/4/95 letter returned FOE. Information taken from PCB facility file.		
Warning Letter Comments:			
Facility:	American Brands, Inc.	Date Sent to Facility	6/21/96
Other Name:	(Stanadyne)	Date Received by Facility	6/24/96
EPA Assigned ID #:	33550	Date Response Received by EPA	7/31/96
		Date of Letter	7/26/96
Contact:	Kenton R. Rose		
Address:	510 Lake Cook Rd., #175		
	Deerfield IL 60015		
Phone:	847-831-0606		
104(e) Response Comments:	8/4/95 letter returned FOE. This facility has no knowledge or records regarding shipments made to PCB. Information taken from PCB facility file.		
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO	
Facility:	American Electric Corporation	Date Sent to Facility	8/ 4/95	5/21/96
Other Name:		Date Received by Facility	8/ 7/95	5/31/96
EPA Assigned ID #:	10675	Date Response Received by EPA		6/14/96
		Date of Letter		6/ 7/96
Contact:	Maxwell Cobb			
Address:	523 S. Ellis Road			
	Jacksonvill FL 32254			
Phone:				
104(e) Response Comments:				
Warning Letter Comments: Records were destroyed by fire in 1982 Company filed bankruptcy in 1984. Information taken from PCB facility file.				
Facility:	American Home Products	Date Sent to Facility	8/ 4/95	
Other Name:	(Shulton Inc.)	Date Received by Facility	8/ 9/95	
EPA Assigned ID #:	32575	Date Response Received by EPA	9/11/95	
		Date of Letter	9/ 8/95	
Contact:	Margaret R. Tribble, Esq.			
Address:	Five Giralda Farms			
	Madison NJ 07940			
Phone:	201-660-5000			
104(e) Response Comments: Unable to locate PCB facility file for HWM #NJ0165459.				
Warning Letter Comments:				
Facility:	American Mobile Oil Purification	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility		
EPA Assigned ID #:	10700	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	2022 US Route 130 N			
	Burlington NJ 08016			
Phone:				
104(e) Response Comments: Green card was signed and returned with no postmark date. No response received. Information taken from PCB facility file.				
Warning Letter Comments:				



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Amoco Pipeline Company	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	10850	<b>Date Response Received by EPA</b>	11/ 8/95
		<b>Date of Letter</b>	11/ 6/95
<b>Contact:</b>	Paul Ressmeyer		
<b>Address:</b>	375 Northridge Rd, #600		
	Atlanta GA 30350-3323		
<b>Phone:</b>	770-512-6863		
<b>104(e) Response Comments:</b> Response includes information for both Sugar Creek facilities.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Amoco of Mora	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	10825	<b>Date Response Received by EPA</b>	
		<b>Date of Letter</b>	
<b>Contact:</b>			
<b>Address:</b>			
	Mora MN 55051		
<b>Phone:</b>			
<b>104(e) Response Comments:</b> No signed green card has been returned and no returned mail has been received. No response. Information taken from PCB facility file.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Anoka State Hospital	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	11000	<b>Date Response Received by EPA</b>	6/20/96
		<b>Date of Letter</b>	6/17/96
<b>Contact:</b>	Corwin Randleman		
<b>Address:</b>	3300 4th Ave. N.		
	Anoka MN 53303		
<b>Phone:</b>			
<b>104(e) Response Comments:</b>			
<b>Warning Letter Comments:</b> Generator reported concentration <5ppm. Facility file reported concentration 1,237 ppm.			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	Arlington Elec. Water Department	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 8/95	
EPA Assigned ID #:	11125	Date Response Received by EPA	8/21/95	
		Date of Letter	8/18/95	
Contact:	Ross Arneson			
Address:	312 W. Alden Street			
	Arlington MN 55307			
Phone:	612-964-5753			
104(e) Response Comments: Generator 104(e) response reports 17 caps sent to PCB. Facility file capacitor log shows 25 caps were received.				
Warning Letter Comments:				
Facility:	Arlington Light Department	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	11150	Date Response Received by EPA	9/11/95	
		Date of Letter	9/ 8/95	
Contact:	Curt Tuttle			
Address:	203 W. Elm, Drawer 379			
	Arlington SD 57212-037			
Phone:	605-983-5251			
104(e) Response Comments: Generator claims that no shipments were made to PCB. Information taken from PCB facility file.				
Warning Letter Comments:				
Facility:	Arrow Forklift Parts, Incorporated	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	11175	Date Response Received by EPA	9/ 8/95	
		Date of Letter	9/ 1/95	
Contact:	Monica Fries			
Address:	1620 Oakland			
	Kansas City MO 64126			
Phone:	314-421-4800			
104(e) Response Comments: Generator has no knowledge or records regarding equipment sent to PCB. Info taken from PCB facility file.				
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Ashland Chemical Company	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	11225	Date Response Received by EPA	10/ 6/95
		Date of Letter	10/ 4/95
Contact:	Stephen Leermakers		
Address:	PO Box 2219		
	Columbus OH 43215		
Phone:	614-790-4261		
104(e) Response Comments:	Generator was unable to locate any documents regarding shipments to PCB. Info taken from facility file.		
Warning Letter Comments:			
Facility:	B.F. Goodrich	Date Sent to Facility	
Other Name:		Date Received by Facility	
EPA Assigned ID #:	13275	Date Response Received by EPA	
		Date of Letter	
Contact:	Mary Schulz		
Address:	11120 S. Norwalk Bl		
	Sante Fe Springs CA 90670		
Phone:			
104(e) Response Comments:	BF Goodrich sent capacitors to North American Environmental. NAE sent to PCB. The PCB facility file for disposal manifest #0720 can be located under North American Env.		
Warning Letter Comments:			
Facility:	BASF Corporation	Date Sent to Facility	6/21/96
Other Name:	(Inmont Corporation)	Date Received by Facility	6/24/96
EPA Assigned ID #:	23100	Date Response Received by EPA	8/30/96
		Date of Letter	8/26/96
Contact:	Nancy Lake Martin		
Address:	3000 Continental Dr. North		
	Mount Olive NJ 07828-1234		
Phone:	201-426-2600		
104(e) Response Comments:	8/4/95 letter returned "FOE." BASF is responding for both Inmont facilities however, they are not able to locate any records pertaining to shipments made to PCB. Info from fac file.		
Warning Letter Comments:			
Prepared by Dynamac Corporation			
Comment.DBF/J 1/21/97			

Page 10

**PCB Treatment, Inc. General Information**  
*Review of Facilities Requiring Follow-up and Warning Letters*

**GENERAL INFORMATION**

**104(e) LETTER INFO**

**WARNING LETTER INFO**

**Facility:** Beaver, City of  
**Other Name:** (Beaver City Light & Water Dept)  
**EPA Assigned ID #:** 11850

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 9/95  
**Date Response Received by EPA** 9/ 8/95  
**Date of Letter** 9/30/95

**Contact:** James Dodson  
**Address:** PO Box 349  
 Beaver City NE 68926  
**Phone:** 308-268-7415

**104(e) Response Comments:** Facility does not believe that they ever transported any materials to either PCB site. Facility file shows manifest #0386 and COD.  
**Warning Letter Comments:**

**Facility:** Bedford, City of  
**Other Name:**  
**EPA Assigned ID #:** 14400

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 9/ 8/95  
**Date of Letter** 9/ 7/95

**Contact:** Michael Socha  
**Address:** PO Drawer 807  
 Bedford VA 24523  
**Phone:** 703-586-7171

**104(e) Response Comments:** Combined response with Bedford Municipal Electric.  
**Warning Letter Comments:**

**Facility:** Belyea Company  
**Other Name:**  
**EPA Assigned ID #:** 11950

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA**  
**Date of Letter** 11/ 8/95

**Contact:** John Stanjeski  
**Address:** 43 Howell Street  
 Jersey City NJ 07306  
**Phone:** 201-653-3334

**104(e) Response Comments:** Unable to locate PCB fac file for HWM #3430, #3050, #3044. Two COD for HWM #2710 w/different dates.  
**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** Berky-Dean Electric  
**Other Name:**  
**EPA Assigned ID #:** 12025

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

---

**104(e) LETTER INFO**

8/ 4/95  
8/ 7/95

---

**WARNING LETTER INFO**

5/21/96  
5/28/96

**Contact:**  
**Address:** 22 Race Street  
Ambler PA 19002  
**Phone:**

**104(e) Response Comments:** No response has been received. Information taken from PCB facility file.

**Warning Letter Comments:**

---

**Facility:** Bethlehem Steel  
**Other Name:**  
**EPA Assigned ID #:** 12075

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility**  
**Date Response Received by EPA** 10/20/95  
**Date of Letter** 10/19/95

**Contact:** Edwin Wilson  
**Address:** 1170 Eighth Avenue  
Bethlehem PA 18016  
**Phone:** 610-694-6660

**104(e) Response Comments:** Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Information taken from the PCB facility file (red folder).

**Warning Letter Comments:**

---

**Facility:** Beverly Benda  
**Other Name:** (Bill Benda)  
**EPA Assigned ID #:** 12200

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility**  
**Date Response Received by EPA** 9/12/95  
**Date of Letter** 9/ 8/95

**Contact:** A.T. Reddish  
**Address:** PO Box 827  
Alliance NE 69301-0827  
**Phone:** 308-762-1150

**104(e) Response Comments:** Bill Benda is deceased.

**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	Bluc Plains Waste Water Treatment	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	12350	Date Response Received by EPA	10/10/95	
		Date of Letter	10/ 6/95	
Contact:	Arabella W. Teal			
Address:	5000 Overlook Drive			
	Washington DC 20032			
Phone:	202-727-3400			
104(e) Response Comments: Orest Hrycyk of OBG Technical Serv. was responsible for all shipments of material to PCB. Info for HWM #0003 & #3289 was provided by generator (no fac file). Info for HWM #1718B was compiled from PCB facility files. HWM #1718A is associated with HWM#1790				
Warning Letter Comments:				
Facility:	Blue Ridge Mining Company, Incorporated	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility		
EPA Assigned ID #:	12375	Date Response Received by EPA		
		Date of Letter		
Contact:	Tom Bazicevic			
Address:	Box 63			
	Luttrell TN 37779			
Phone:				
104(e) Response Comments: No returned mail, signed green card, or response. Unable to locate PCB facility or Session file. No information has been entered into the Equipment Database.				
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Board of Public Utilities  
**Other Name:**  
**EPA Assigned ID #:** 12400

**Contact:** Marynell Hollenbeck  
**Address:** 700 Minnesota Avenue  
Kansas City KS 66101  
**Phone:** 913-573-9000

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) LETTER INFO**

8/ 4/95  
8/ 7/95  
9/ 8/95  
9/ 7/95

**WARNING LETTER INFO**

**104(e) Response Comments:** Gen. sent oil & cap. to Env. Int'l under HWM #8601 & #8602. See Env. Int'l for more info. Gen. submitted COD only for HWM #2628. There is no fac. file for this HWM. Info for HWM #2516, #2100, & #2737 was taken from PCB fac files only & not from 104(e).

**Warning Letter Comments:**

**Facility:** Bonguard Municipal  
**Other Name:**  
**EPA Assigned ID #:** 12500

**Contact:**  
**Address:** Fridley MN 55432  
**Phone:**

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95

**104(e) Response Comments:** No returned mail - no response. Information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** Boone Rural Electric Membership Corporati  
**Other Name:** (Boon County REMC)  
**EPA Assigned ID #:** 12525

**Contact:** Dale Geiselman, CEO  
**Address:** Box 563  
Lebanon IN 46052  
**Phone:** 317-482-2390

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95  
9/11/95  
9/ 6/95

**104(e) Response Comments:** For more info, contact Pat Hyer, Mark Lautenschlager, & Charles Muellelr, High Voltage Maint., 5230 Commerce Circle, Indianapolis, ID 46237. HVM was the destruct & storage contractor who shipped cap. to PCB, Inc. See HVM 104(e) resp. summary.

**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Bowling Green, City of	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95
<b>EPA Assigned ID #:</b>	14475	<b>Date Response Received by EPA</b>	9/12/95
		<b>Date of Letter</b>	9/ 9/95
<b>Contact:</b>	Daryl D. Stockburger		
<b>Address:</b>	304 N. Church Street		
	Bowling Green OH 43402		
<b>Phone:</b>	419-354-6246		
<b>104(e) Response Comments:</b> HWM #3759, #4133, and #2101 show High Voltage Maintenance (HVM) as TSD. See HVM for more info on these manifests.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Bradley Resources Company	<b>Date Sent to Facility</b>	6/21/96
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	12725	<b>Date Response Received by EPA</b>	
		<b>Date of Letter</b>	
<b>Contact:</b>			
<b>Address:</b>	Box 292		
	Wellsville NY 14895		
<b>Phone:</b>			
<b>104(e) Response Comments:</b> 8/4/95 letter returned FOE. FU 6/21/96 letter sent to Coudersport, PA returned "attempted, not known." Information taken from PCB facility file.			
<b>Warning Letter Comments:</b>			



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Bridgeport Brass Corporation	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95
<b>EPA Assigned ID #:</b>	12800	<b>Date Response Received by EPA</b>	9/18/95
		<b>Date of Letter</b>	9/15/95
<b>Contact:</b>	Monica Fries		
<b>Address:</b>	Box 51519		
	Indianapolis IN 46251		
<b>Phone:</b>	317-244-2461		
<b>104(e) Response Comments:</b>	Generator contracted High Voltage Maintenance (HVM) & SCA Chemicals to dispose of capacitors & debris. Generator provided info regarding shipments to HVM		
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Brookings Municipal Utilities	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	12850	<b>Date Response Received by EPA</b>	9/ 7/95
		<b>Date of Letter</b>	9/ 1/95
<b>Contact:</b>	Andy Jensen Util Mgr.		
<b>Address:</b>	525 Western Avenue		
	Brookings SD 57006		
<b>Phone:</b>			
<b>104(e) Response Comments:</b>	Other contact: Lisa Dowden, Spiegel & McDiarmid, 1350 New York Ave., NW, #1100, Wash, DC, 20005-4798. Weights for transformers include weight of drained oil which was sent in separate drums on HWM #0032A & #0003.		
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
*Review of Facilities Requiring Follow-up and Warning Letters*

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Buffalo General Hospital	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 9/95
EPA Assigned ID #:	13000	Date Response Received by EPA	8/21/95
		Date of Letter	8/15/95
Contact:	Mary DeLeys		
Address:	100 High Street		
	Buffalo NY 14203		
Phone:	716-845-5600		
104(e) Response Comments: Response includes information for Deaconess Hospital (17475) but none for Buffalo Hospital. Information for Buffalo General taken from PCB facility file.			
Warning Letter Comments:			
Facility:	Bunge Corporation	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 8/95
EPA Assigned ID #:	13025	Date Response Received by EPA	9/ 6/95
		Date of Letter	9/ 5/95
Contact:	Loren Polak		
Address:	11720 Borman Dr.		
	St. Louis MO 63146		
Phone:	314-872-3030		
104(e) Response Comments: Response received on 9/6/95 - Respondent claims they did not engage in the transportation of any materials to PCB. Second response received 8/9/96 includes information regarding equipment sent to PCB. Response for both locations.			
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** Butler Taconite  
**Other Name:**  
**EPA Assigned ID #:** 13200  
  
**Contact:** Christopher Anderson  
**Address:** 200 Public Square, Ste. 36-5  
Cleveland OH 44114-2304  
  
**Phone:**

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 8/95  
**Date Response Received by EPA** 9/ 1/95  
**Date of Letter** 8/30/95

---

**104(e) LETTER INFO**

---

**WARNING LETTER INFO**

---

**104(e) Response Comments:** COD was not enclosed with the 104(e) response. A destruction date was given under question 7A. No COD in file.  
**Warning Letter Comments:**

---

**Facility:** By-Products Management/United  
**Other Name:**  
**EPA Assigned ID #:** 13250  
  
**Contact:**  
**Address:** 1150 Junction Avenue  
Schererville IN 46375  
  
**Phone:**

**Date Sent to Facility** 6/21/96  
**Date Received by Facility** 6/24/96  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) Response Comments:** 8/4/95 letter returned "attempted, not known." No response received. Unable to locate PCB facility file. No equipment information in database.  
**Warning Letter Comments:**

---

**Facility:** C.C. Engineering Incorporated  
**Other Name:**  
**EPA Assigned ID #:** 16775  
  
**Contact:**  
**Address:** 2200 85th Avenue North  
Brooklyn Park MN 55444  
  
**Phone:**

**Date Sent to Facility** 6/21/96  
**Date Received by Facility** 6/24/96  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) Response Comments:** 8/4/95 letter returned "attempted, not known." No response received. Information taken from PCB facility file.  
**Warning Letter Comments:**

---

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** CEM Stone Products  
**Other Name:**  
**EPA Assigned ID #:** 13850

**Date Sent to Facility** 6/21/96  
**Date Received by Facility** 6/24/96  
**Date Response Received by EPA** 7/12/96  
**Date of Letter** 7/ 8/96

---

**104(e) LETTER INFO**

---

**WARNING LETTER INFO**

**Contact:** Tim Becken  
**Address:** 2025 Centre Pointe Blvd., St  
Mendota Heights MN 55120-1221  
**Phone:** 612-688-9292

**104(e) Response Comments:** 8/4/95 letter returned "attempted, not known". Generator has no knowledge of information regarding equipment sent to PCB. Information taken from PCB facility file.

**Warning Letter Comments:**

---

**Facility:** Cannon-Muskegon Corporation  
**Other Name:**  
**EPA Assigned ID #:** 13425

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 9/29/95  
**Date of Letter** 9/28/95

**Contact:** Dennis R. Shea  
**Address:** 101 Greenwood Ave., #470  
Jenkintown PA 19046  
**Phone:** 215-517-2023

**104(e) Response Comments:** Subsidiary of SPS Technologies, Inc.

**Warning Letter Comments:**

---

**Facility:** Cardington Lincoln Public School  
**Other Name:**  
**EPA Assigned ID #:** 13525

**Date Sent to Facility** 8/ 4/95 5/21/96  
**Date Received by Facility** 8/ 7/95 5/29/96  
**Date Response Received by EPA**  
**Date of Letter**

**Contact:** Board of Education  
**Address:** 349 Chesterville Av  
Cardington OH 43315  
**Phone:**

**104(e) Response Comments:**

**Warning Letter Comments:** No response has been received from this facility. Information taken from PCB facility file.

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** Cargill  
**Other Name:** (Ross Cargill Company & Ross Industries)  
**EPA Assigned ID #:** 31625

**Contact:** LeRaye M Osborne  
**Address:** PO Bos 5624  
Minneapolis MN 55440  
**Phone:** 612-742-6374

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 9/12/95  
**Date of Letter** 9/ 7/95

---

**104(e) LETTER INFO**

---

**WARNING LETTER INFO**

**104(e) Response Comments:** Response includes information for Ross Industries (HWM 0571) and Russ Cargill Company (HWM 2164). No info was provided for HWM 2481.  
**Warning Letter Comments:** Warning letter sent in error.

---

**Facility:** Carlson Park Associates  
**Other Name:**  
**EPA Assigned ID #:** 13575

**Contact:**  
**Address:** 100 Carlson Road  
Rochester NY 14610  
**Phone:**

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) Response Comments:** No signed green card has been returned and no 104(e) response has been received. Information taken from PCB facility file.  
**Warning Letter Comments:**

---

**Facility:** Carlton College  
**Other Name:**  
**EPA Assigned ID #:** 13600

**Contact:** R.E. Lutz  
**Address:** 1 North College St.  
Northfield MN 55057  
**Phone:** 507-663-4133

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility**  
**Date Response Received by EPA** 9/11/95  
**Date of Letter** 9/ 6/95

**104(e) Response Comments:** The capacitor processing log in facility file for HWM #0948 is illegible.  
**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

<b>GENERAL INFORMATION</b>		<b>104(e) LETTER INFO</b>	<b>WARNING LETTER INFO</b>
<b>Facility:</b>	Carmi Water & Light	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	13625	<b>Date Response Received by EPA</b>	6/ 3/96
		<b>Date of Letter</b>	5/31/96
<b>Contact:</b>	James T. Gaines, Mayor		
<b>Address:</b>	227 Main Street		
	Carmi IL 62821		
<b>Phone:</b>			
<b>104(e) Response Comments:</b>			
<b>Warning Letter Comments:</b> Person listed in counsel section is second party to receive future mailing.			
<b>Facility:</b>	Carnation Maintenance Company	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(Carnation Company)	<b>Date Received by Facility</b>	8/ 8/95
<b>EPA Assigned ID #:</b>	13650	<b>Date Response Received by EPA</b>	5/31/96
		<b>Date of Letter</b>	5/27/96
<b>Contact:</b>	Jung Ho Lee		
<b>Address:</b>	830 E. Acacia Ave. #A		
	Glendale CA 91205		
<b>Phone:</b>	818-500-9916		
<b>104(e) Response Comments:</b>			
<b>Warning Letter Comments:</b> Generator has no knowledge or information regarding shipments made to PCB. Unable to locate PCB facility file. Information taken from HWM found in "Session file."			
<b>Facility:</b>	Cashton Wisconsin, Village of	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	36700	<b>Date Response Received by EPA</b>	8/10/95
		<b>Date of Letter</b>	8/ 9/95
<b>Contact:</b>	John Hauser		
<b>Address:</b>	709 Main Street		
	Cashton WI 54619		
<b>Phone:</b>	608-654-7828		
<b>104(e) Response Comments:</b> Generator has no knowledge or information regarding equipment sent to PCB. Unable to locate any facility files for this generator.			
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	Cassandra Corporation	Date Sent to Facility	8/ 4/95	
Other Name:	(South Bend Lathe)	Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	32850	Date Response Received by EPA	9/11/95	
		Date of Letter	9/ 2/95	
Contact:	James Carr			
Address:	52325 Briarcliff Lane			
	South Bend IN 46635			
Phone:				
104(e) Response Comments: Cassandra Corp is "debtor-in-possession" of South Bend Lathe. Generator is bankrupt & Cassandra is not in possession of any books or records. Info on HWM 1496 is included in Delta Star Response.				
Warning Letter Comments:				
Facility:	Caterpillar Incorporated	Date Sent to Facility	8/ 4/95	
Other Name:	(Caterpillar Tractor Co.)	Date Received by Facility	8/ 8/95	
EPA Assigned ID #:	13725	Date Response Received by EPA	10/16/95	
		Date of Letter	10/16/95	
Contact:	David Howe			
Address:	100 NE Adams St.			
	Peoria IL 61629			
Phone:				
104(e) Response Comments: Other RCRA ID #: Mapleton, IL Plant ILD05266436 and Mossville, IL Plant ILD005244777.				
Warning Letter Comments:				
Facility:	Centec Analytical Services	Date Sent to Facility	6/21/96	
Other Name:		Date Received by Facility	6/25/96	
EPA Assigned ID #:	13875	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	1401 Municipal Rd NW			
	Roanoke VA 24012			
Phone:				
104(e) Response Comments: 8/4/95 letter returned "FOE." No response has been received. Information taken from PCB facility file.				
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Central Prison  
**Other Name:**  
**EPA Assigned ID #:** 13975

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) LETTER INFO**

6/21/96

**WARNING LETTER INFO**

**Contact:**  
**Address:** 1000 Mumford  
Raleigh NC 27601  
**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned "incorrect address " 6/21/96 letter returned "refused" Unable to locate PCB facility files for this facility. No equipment information has been entered into the database.

**Warning Letter Comments:**

**Facility:** CertainTeed Corporation  
**Other Name:**  
**EPA Assigned ID #:** 14075

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/10/95  
**Date Response Received by EPA** 10/16/95  
**Date of Letter** 10/12/95

**Contact:** Lauren P. Alterman, CNS  
**Address:** 750 E. Swedesford Rd.  
Valley Forge PA 19482-0101  
**Phone:** 215-341-7000

**104(e) Response Comments:** Wholly owned subsidiary of Saint-Gobain Corporation. Other RCRA ID #NJD041746843.

**Warning Letter Comments:**

**Facility:** Champlin Petroleum Company  
**Other Name:**  
**EPA Assigned ID #:** 14150

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**Contact:**  
**Address:** 420 Henry Ford Aven  
Wilmington CA 90744-676  
**Phone:**

**104(e) Response Comments:** Information request letter returned by Ultramar Inc. with instructions to resend to Union Pacific Resources Co. in Ft. Worth. TX. Information taken from PCB facility file.

**Warning Letter Comments:**



**PCB Treatment, Inc. General Information**  
*Review of Facilities Requiring Follow-up and Warning Letters*

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	Clyde Iron	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>	(Clyde Company)	<b>Date Received by Facility</b>		
<b>EPA Assigned ID #:</b>	15750	<b>Date Response Received by EPA</b>	9/15/95	
		<b>Date of Letter</b>	9/10/95	
<b>Contact:</b>	Thomas Hoban			
<b>Address:</b>	102 South 29th Aven Duluth MN 55806			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> Generator has no knowledge or documents pertaining to shipments made to PCB. Info taken from PCB facility file.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Coleman County Electric Cooperative	<b>Date Sent to Facility</b>	6/21/96	
<b>Other Name:</b>		<b>Date Received by Facility</b>	6/25/96	
<b>EPA Assigned ID #:</b>	15925	<b>Date Response Received by EPA</b>	7/22/96	
		<b>Date of Letter</b>	7/18/96	
<b>Contact:</b>	Al Nunez			
<b>Address:</b>	PO Box 860 Coleman TX 76834-0860			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> 8/4/95 letter returned "FOE."				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Coleman, City of	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>	(Coleman Municipal Light & Power)	<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	15950	<b>Date Response Received by EPA</b>	9/15/95	
		<b>Date of Letter</b>	9/14/95	
<b>Contact:</b>	David Sooter			
<b>Address:</b>	PO Box 592, 200 W. Liveoak Coleman TX 76834			
<b>Phone:</b>	915-625-5114			
<b>104(e) Response Comments:</b> Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Information taken from the PCB facility file (red folder).				
<b>Warning Letter Comments:</b>				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**104(e) LETTER INFO**

**WARNING LETTER INFO**

**Facility:** Commerce Building  
**Other Name:**  
**EPA Assigned ID #:** 16125

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95

**Contact:**  
**Address:** 8 East 4th Street  
St. Paul MN 55101  
**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned "insufficient address." Information taken from PCB facility file.  
**Warning Letter Comments:**

**Facility:** Communications Satellite Corporation  
**Other Name:**  
**EPA Assigned ID #:** 16150

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

6/21/96  
6/24/96  
7/ 2/96  
7/ 2/96

**Contact:** Don Fifeld  
**Address:** 6560 T Rock Springs Drive  
Bethesda MD 20817  
**Phone:**

**104(e) Response Comments:** 8/4/95 mail sent to Bethesda, MD and Carmel Valley, CA returned "addressee unknown." FU letter sent to El Segundo, CA. Respondent has no knowledge of equipment sent to PCB. Info taken from PCB facility files.  
**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Compton Electrical Equipment Company  
**Other Name:**  
**EPA Assigned ID #:** 16200

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) LETTER INFO**

8/ 4/95

**WARNING LETTER INFO****Contact:**

**Address:** 103 Thompson Road B  
Culloden WV 25510

**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned "moved-not forwardable." Equipment information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** Conoco Inc.  
**Other Name:** (Conoco Oil Company)  
**EPA Assigned ID #:** 16225

**Date Sent to Facility** 6/21/96  
**Date Received by Facility** 6/24/96  
**Date Response Received by EPA**  
**Date of Letter** 8/23/96

**Contact:** Jon-Al Duplantier  
**Address:** 600 N. Dairy Ashford, #2034  
Houston TX 77079-6651  
**Phone:** 713-293-1044

**104(e) Response Comments:** 8/4/95 letter returned "FOE." Respondent has no knowledge of information regarding shipments sent to PCB. Information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** Consolidated Cigar Corporation  
**Other Name:**  
**EPA Assigned ID #:** 16250

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 8/23/95  
**Date of Letter** 8/21/95

**Contact:** J. McGoff  
**Address:** McAdoo & Tresckow R  
McAdoo PA 18237  
**Phone:** 717-929-2355

**104(e) Response Comments:** Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Information taken from the PCB facility file (red folder).

**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**104(e) LETTER INFO**

**WARNING LETTER INFO**

**Facility:** Contel Data Center  
**Other Name:**  
**EPA Assigned ID #:** 16325

**Date Sent to Facility** 6/21/96  
**Date Received by Facility** 6/24/96  
**Date Response Received by EPA** 7/16/96  
**Date of Letter** 7/ 9/96

**Contact:**  
**Address:** 900 Walnut  
St. Louis MO 63102-113  
**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned "Unknown." Response to FU letter received from GTE Customer Networks suggests letter be sent to Contel Corp, c/o GTE Corp, One Stamford Forum, Stamford, CT 06904, Attn: Legal Dept. Information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** Cottage Grove High School  
**Other Name:**  
**EPA Assigned ID #:** 16475

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**Contact:**  
**Address:** 8040 80th Street So  
Cottage Gro MN 55016  
**Phone:**

**104(e) Response Comments:** No returned mail, no green card, no response. Equipment information taken from PCB facility file.

**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
*Review of Facilities Requiring Follow-up and Warning Letters*

<b>GENERAL INFORMATION</b>		<b>104(e) LETTER INFO</b>	<b>WARNING LETTER INFO</b>
<b>Facility:</b>	Cowlitz County PUD	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	16500	<b>Date Response Received by EPA</b>	9/ 1/95
		<b>Date of Letter</b>	8/29/95
<b>Contact:</b>	Dennis P. Robinson		
<b>Address:</b>	960 Commerce Avenue		
	Longview WA 98632		
<b>Phone:</b>	206-423-2210		
<b>104(e) Response Comments:</b> Unable to locate PCB facility file.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Crouse-Hinds Company	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	16600	<b>Date Response Received by EPA</b>	9/ 8/95
		<b>Date of Letter</b>	9/ 7/95
<b>Contact:</b>	W. Anne Lemelle		
<b>Address:</b>	Wolf & 7th North St		
	Syracuse NY 13208		
<b>Phone:</b>	713-739-5658		
<b>104(e) Response Comments:</b> Unable to locate PCB facility files.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Crow Wing Coop Power & Light Company	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	16625	<b>Date Response Received by EPA</b>	8/18/95
		<b>Date of Letter</b>	8/16/95
<b>Contact:</b>	Douglas Kraklau		
<b>Address:</b>	PO Box 507		
	Brainerd MN 56401		
<b>Phone:</b>	218-829-2827		
<b>104(e) Response Comments:</b> Generator has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.			
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO	
Facility:	Cuyahoga Falls, City of	Date Sent to Facility	8/ 4/95	5/21/96
Other Name:		Date Received by Facility	8/ 8/95	5/24/96
EPA Assigned ID #:	14675	Date Response Received by EPA		6/24/96
		Date of Letter		6/21/96
Contact:	Barbara Rettig Bailey			
Address:	2310 Second St.			
	Cuyahoga Falls OH 44221			
Phone:	330-971-8190			
104(e) Response Comments:				
Warning Letter Comments: Unable to locate PCB facility files for HWM #1230 and 0880. Information taken from 104(e) response.				
Facility:	Cyclops Corporation	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	16700	Date Response Received by EPA	9/27/95	
		Date of Letter	9/26/95	
Contact:				
Address:	Sawhill Tubular Div			
	Wheatland PA 16161			
Phone:				
104(e) Response Comments: Resp submitted by Armco Inc., on behalf of Cyclops Corp Sawhill Tubular Division, Cyclops Corporation, and Cytemp Specialty Steel Division. All correspondence is to be sent directly to Armco Legal Dept. Other RCRA ID are PAD045874138 and PAD004392742.				
Warning Letter Comments:				
Facility:	D&G Fraser Inc	Date Sent to Facility	8/ 4/95	
Other Name:	(Powell's Inc.)	Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	30450	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	5780 Lincoln Drive			
	Edina MN 55436			
Phone:				
104(e) Response Comments: Letter dated 9/26/95 from Sathers, new owner as of 11/25/91, requested letter be sent to D&G Fraser Inc (formerly Powell's, Inc.) for information regarding shipments made to PCB. No response. Equipment information taken from PCB facility file.				
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
*Review of Facilities Requiring Follow-up and Warning Letters*

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Dahlberg Light & Power	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	16800	<b>Date Response Received by EPA</b>	8/28/95
		<b>Date of Letter</b>	8/24/95
<b>Contact:</b>	Wayne C. Schirmer		
<b>Address:</b>	9221 E. Main, PO Box 300		
	Solon Springs WI 54873-0300		
<b>Phone:</b>	715-378-2205		
<b>104(e) Response Comments:</b> Generator reports 37 cap were sent on HWM #0124. Facility file cap log shows 65 cap were received.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Dairyland Power Cooperative	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	16850	<b>Date Response Received by EPA</b>	9/ 7/95
		<b>Date of Letter</b>	9/ 6/95
<b>Contact:</b>	Eric Hennen		
<b>Address:</b>	3200 E. Ave. S, PO Box 817		
	LaCrosse WI 54602-0817		
<b>Phone:</b>	608-787-1371		
<b>104(e) Response Comments:</b> Dairyland Power Coop unable to locate PCB facility file for HWM #1088.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Dakota Energy Cooperative, Incorporated	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(Beadle Electric Cooperative, Inc.)	<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	11800	<b>Date Response Received by EPA</b>	9/11/95
		<b>Date of Letter</b>	9/ 6/95
<b>Contact:</b>	Larry Brink		
<b>Address:</b>	East Highway 14, PO Box 83		
	Huron SD 57350-0830		
<b>Phone:</b>	605-352-8591		
<b>104(e) Response Comments:</b> Response includes information for East River Power Coop.			
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
*Review of Facilities Requiring Follow-up and Warning Letters*

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Dana Corporation	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	17125	<b>Date Response Received by EPA</b>	9/ 8/95
		<b>Date of Letter</b>	9/ 5/95
<b>Contact:</b>	Lisa Wurster		
<b>Address:</b>	PO Box 1000		
	Toledo OH 43697		
<b>Phone:</b>	419-535-4675		
<b>104(e) Response Comments:</b>	The generator holds the following EPA ID #'s: IND094577095 (Syracuse, Ind), IND980503841 (Richmond, Ind), IND040289357 (Hagerstown, Ind), IND980504229 (CAMSHAFT) and IND094558004 (Leader Industries).		
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Davidson College	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	17250	<b>Date Response Received by EPA</b>	9/11/95
		<b>Date of Letter</b>	9/ 7/95
<b>Contact:</b>	Benne C. Hutson		
<b>Address:</b>	PO Box 31247		
	Charlotte NC 28231		
<b>Phone:</b>	704-373-2060		
<b>104(e) Response Comments:</b>	Generator has no knowledge of shipments sent to PCB. Unable to locate any PCB facility files. No information has been entered into the equipment database.		
<b>Warning Letter Comments:</b>			



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** Dayton Hudson Corporation  
**Other Name:** (Dayton's-Nicolette Mall)  
**EPA Assigned ID #:** 17375

**Contact:** Nancy Husnick, Law Clerk  
**Address:** 700 Nicollet Mall  
Minneapolis MN 55402  
**Phone:**

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility**  
**Date Response Received by EPA** 10/ 2/95  
**Date of Letter** 9/28/95

---

**104(e) LETTER INFO**

---

**WARNING LETTER INFO**

---

**104(e) Response Comments:** Response includes shipment from Minneapolis location (HWM #0424).  
**Warning Letter Comments:**

---

**Facility:** Delta Star Electric  
**Other Name:**  
**EPA Assigned ID #:** 17550

**Contact:** Thomas Grabarek, VP  
**Address:** 1125 South Walnut  
South Bend IN 46619  
**Phone:** 219-234-8131

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 8/25/95  
**Date of Letter** 8/21/95

**104(e) Response Comments:** Company claims to be transporter only and have never been an owner or generator of PCB's. Equipment listed was taken from PCB facility files.  
**Warning Letter Comments:**

---

**Facility:** Delta-Montrose Electric Association  
**Other Name:**  
**EPA Assigned ID #:** 17525

**Contact:** Steven M. Metheny  
**Address:** 121 E. 12th St., Box 59  
Delta CO 81416  
**Phone:** 970-874-8081

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 8/95  
**Date Response Received by EPA** 9/ 1/95  
**Date of Letter** 8/29/95

**104(e) Response Comments:** EPA ID # for Read, Colo location is COD983773797.  
**Warning Letter Comments:**

---

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Demeter Agro Incorporated  
**Other Name:**  
**EPA Assigned ID #:** 17575

**Contact:**  
**Address:** 3110 California Str  
Minneapolis MN 55418  
**Phone:**

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) LETTER INFO**

8/ 4/95  
8/ 7/95

**WARNING LETTER INFO**

5/21/96  
5/24/96

**104(e) Response Comments:** No response received. Information taken from PCB facility file.  
**Warning Letter Comments:**

*received  
8/26/97*

*N*

**Facility:** Department of Public Utilities  
**Other Name:** (Orangeburg Dept. of Public Utilities)  
**EPA Assigned ID #:** 29400

**Contact:** David E. Gillam  
**Address:** Box 1057  
Orangeburg SC 29116  
**Phone:** 803-534-2821

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 8/95  
**Date Response Received by EPA** 8/28/95  
**Date of Letter** 8/23/95

**104(e) Response Comments:** Unable to locate PCB facility files for this generator.  
**Warning Letter Comments:**

**Facility:** Dickens Electric Cooperative  
**Other Name:**  
**EPA Assigned ID #:** 17750

**Contact:** Michael Packard Op  
**Address:** Box 309  
Spur TX 79370  
**Phone:**

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA**  
**Date of Letter**

*rec  
8/4/97*

*N*

**104(e) Response Comments:** No response received. Information taken from PCB facility file.  
**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Douglas Corporation	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	17875	<b>Date Response Received by EPA</b>	9/ 7/95
		<b>Date of Letter</b>	9/ 5/95
<b>Contact:</b>	John Fudala		
<b>Address:</b>	3520 Xenwood Ave. South		
	St. Louis Park MN 55416-2394		
<b>Phone:</b>	612-929-0484		
<b>104(e) Response Comments:</b>			
<b>Warning Letter Comments:</b> Combined response with SK Products (wholly owned subsidiary of Douglas Corp).			
<b>Facility:</b>	Douglas Electric Cooperative, Incorporated	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	17900	<b>Date Response Received by EPA</b>	9/ 8/95
		<b>Date of Letter</b>	8/31/95
<b>Contact:</b>	Merlin Goehring		
<b>Address:</b>	PO Box 370		
	Armour SD 57313		
<b>Phone:</b>	602-724-2323		
<b>104(e) Response Comments:</b> Combined response with SK Products (wholly owned subsidiary of Douglas Corporation).			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Dover, City of	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95
<b>EPA Assigned ID #:</b>	14775	<b>Date Response Received by EPA</b>	9/ 7/95
		<b>Date of Letter</b>	9/ 6/95
<b>Contact:</b>	Jim O'Connor		
<b>Address:</b>	Box 475		
	Dover DE 19903-0475		
<b>Phone:</b>	302-736-7005		
<b>104(e) Response Comments:</b> Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Info taken from facility file.			
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** Dresser Industries  
**Other Name:** (Worthington Pump Div. of Dress)  
**EPA Assigned ID #:** 38275

**Date Sent to Facility** 6/21/96  
**Date Received by Facility** 6/25/96  
**Date Response Received by EPA** 7/29/96  
**Date of Letter** 7/26/96

**104(e) LETTER INFO****WARNING LETTER INFO**

---

**Contact:** LeRoy DeNooyer  
**Address:** PO Box 718  
Dallas TX 75221  
**Phone:** 214-740-6075

**104(e) Response Comments:** 8/4/95 letter returned - out of business. This generator has no knowledge or information regarding shipments sent to PCB. Information taken from PCB facility file.

**Warning Letter Comments:**

---

**Facility:** Drummond Dolomite Incorporated  
**Other Name:**  
**EPA Assigned ID #:** 18025

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 9/27/95  
**Date of Letter** 9/20/95

**Contact:** David J. Richards  
**Address:** HC #53 Box 529  
Drummond Is MI 49726  
**Phone:**

**104(e) Response Comments:** Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Info taken from the PCB facility file. See 104(e) response for corporate ownership information.

**Warning Letter Comments:**

---

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

<b>GENERAL INFORMATION</b>		<b>104(e) LETTER INFO</b>	<b>WARNING LETTER INFO</b>
<b>Facility:</b>	Dynex Industries, Inc.	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(Electric Equipment Service Corporation)	<b>Date Received by Facility</b>	6/21/96
<b>EPA Assigned ID #:</b>	18625	<b>Date Response Received by EPA</b>	6/24/96
		<b>Date of Letter</b>	8/26/96
<b>Contact:</b>	Brian Sjoberg		8/22/96
<b>Address:</b>	4751 Mustang Circle		
	St. Paul MN 55112		
<b>Phone:</b>	612-784-4040		
<b>104(e) Response Comments:</b> 104(e) information request letter returned FOE			
<b>Warning Letter Comments:</b> Dynex Industries included a customer list with their response which would indicate that they are also a broker.			
<b>Facility:</b>	E.I. DuPont de Nemours	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	19175	<b>Date Response Received by EPA</b>	10/10/95
		<b>Date of Letter</b>	10/ 6/95
<b>Contact:</b>	Nancy A. Sandell		
<b>Address:</b>	1007 Market Street		
	Wilmington DE 19898		
<b>Phone:</b>	302-774-4406		
<b>104(e) Response Comments:</b> One response was received for all facilities.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	ENSR	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(Sunohio/Release 781)	<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	34525	<b>Date Response Received by EPA</b>	11/15/95
		<b>Date of Letter</b>	11/14/95
<b>Contact:</b>	Robert Reno		
<b>Address:</b>	1700 Gateway Blvd. SE		
	Canton OH 44707		
<b>Phone:</b>	216-452-0837		
<b>104(e) Response Comments:</b> Information included under ENSR Operations (34500).			
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** ETI of North America

**Other Name:**

**EPA Assigned ID #:** 19100

**Contact:** Ted Topolski Jr. O

**Address:** Box 7784  
Overland Park KS 66207

**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned FOE. Equipment information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** East End Mutual Electric Company

**Other Name:**

**EPA Assigned ID #:** 18200

**Contact:**

**Address:** 528 E. Street  
Rupert ID 83350

**Phone:**

**104(e) Response Comments:** No response received. Information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** East Point Electric

**Other Name:**

**EPA Assigned ID #:** 18250

**Contact:**

**Address:** 3120 Bayard Street  
East Point GA 30344

**Phone:**

**104(e) Response Comments:** No response received. Information taken from PCB facility file.

**Warning Letter Comments:**

**104(e) LETTER INFO**

8/ 4/95

**WARNING LETTER INFO**

M

8/ 4/95

5/21/96

8/ 8/95

5/28/96

N

8/ 4/95

8/ 7/95

N

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	East River Electric Power Cooperative	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	18275	Date Response Received by EPA	9/ 1/95	
		Date of Letter	8/30/95	
Contact:	George Colombe			
Address:	121 S.E. First St. Madison SD 57042			
Phone:	605-256-4536			
104(e) Response Comments: HWM #3128, #3682, and #3793 were equipment sent to the Ewing location in Kansas. No facility files were available for these manifests.				
Warning Letter Comments:				
Facility:	East Shoshone Water District	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	18300	Date Response Received by EPA	9/ 5/95	
		Date of Letter	8/25/95	
Contact:	George M. Parks			
Address:	407 7th Street Wallace ID 83873			
Phone:	208-752-1174			
104(e) Response Comments: Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Info taken from the PCB facility file.				
Warning Letter Comments:				
Facility:	Eaton Corporation	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	18375	Date Response Received by EPA	9/ 6/95	
		Date of Letter	9/ 5/95	
Contact:	Camille Corbin			
Address:	East Lincoln Highway Kearney NE 68847			
Phone:	216-523-4515			
104(e) Response Comments: Response includes information for South Bend Forge and Controls Company of America.				
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Educational Testing Service	Date Sent to Facility	6/21/96
Other Name:		Date Received by Facility	6/24/96
EPA Assigned ID #:	18475	Date Response Received by EPA	
		Date of Letter	
Contact:	Eleanor Horne		
Address:	Mail Stop 15-C, Rosedale Rd		
	Princeton NJ 08541		
Phone:			
104(e) Response Comments:	<i>Resp rec 9/30/96, dated 9/24/96</i>		
Warning Letter Comments:	<del>No response received. Equipment information taken from PCB facility file.</del>		
Facility:	Edward Hines, Jr. VA Hospital	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 8/95
EPA Assigned ID #:	39000	Date Response Received by EPA	9/20/95
		Date of Letter	9/18/95
Contact:	Darlene Weisman		
Address:	PO Box 5000		
	Hines IL 60141-5138		
Phone:	708-343-7200		
104(e) Response Comments:	Response received from the Dept of VA. Ms. Weisman can be reached at ext. 5613. Generator has no knowledge or information regarding shipments made to PCB. Info from facility file.		
Warning Letter Comments:			
Facility:	Edwin Stueber	Date Sent to Facility	8/ 4/95
Other Name:	(Edwin Stubber)	Date Received by Facility	8/ 7/95
EPA Assigned ID #:	18500	Date Response Received by EPA	8/18/95
		Date of Letter	8/16/95
Contact:	Edwin Stueber		
Address:	1305 S. Franklin		
	New Ulm MN 56072		
Phone:			
104(e) Response Comments:	104(e) response was inadvertently listed under Electric Equipment Service (broker for Mr. Stueber).		
Warning Letter Comments:	Warning letter sent in error and refused by Mr. Stueber.		



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	El Paso Electric Company	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	18575	<b>Date Response Received by EPA</b>	10/ 6/95	
		<b>Date of Letter</b>	10/ 4/95	
<b>Contact:</b>	Fernando Gireud			
<b>Address:</b>	303 N. Oregon El Paso TX 79901			
<b>Phone:</b>	915-543-2069			
<b>104(e) Response Comments:</b> Unable to locate PCB facility file for HWM: 3663, 3559, 3368, 3369, 3127, 3077, 2587, 3559, and 3664. Weight was calculated for oil sent to the Kansas facility.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Eldon, City of	<b>Date Sent to Facility</b>	8/ 4/95	5/21/96
<b>Other Name:</b>	(Eldon Municipal)	<b>Date Received by Facility</b>	8/ 7/95	5/23/96
<b>EPA Assigned ID #:</b>	18600	<b>Date Response Received by EPA</b>		6/17/96
		<b>Date of Letter</b>		6/12/96
<b>Contact:</b>	Charles M. Kiple			
<b>Address:</b>	Box 308 Eldon IA 52554			
<b>Phone:</b>				
<b>104(e) Response Comments:</b>				
<b>Warning Letter Comments:</b> Generator has no knowledge or information pertaining to shipments made to PCB. Information taken from PCB facility file.				
<b>Facility:</b>	Electric Machinery	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	18650	<b>Date Response Received by EPA</b>	10/10/95	
		<b>Date of Letter</b>	10/ 9/95	
<b>Contact:</b>	LeRoy DeNooyer			
<b>Address:</b>	2001 Ross Avenue Dallas TX 75201			
<b>Phone:</b>	214-740-6075			
<b>104(e) Response Comments:</b> Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Information taken from the PCB facility file (red folder). Direct further correspondence to LeRoy DeNooyer, Dresser Industries, PO Box 718, Dallas, TX 75221.				
<b>Warning Letter Comments:</b>				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION****104(e) LETTER INFO****WARNING LETTER INFO**

---

**Facility:** Electro Sales Company**Other Name:****EPA Assigned ID #:** 18800**Contact:** Richard Berg**Address:** 100 Fellsway W  
Somerville MA 02145**Phone:** 617-666-0500**Date Sent to Facility**

8/ 4/95

**Date Received by Facility**

8/ 8/95

**Date Response Received by EPA**

8/21/95

**Date of Letter**

8/11/95

**104(e) Response Comments:** Generator stated that any records prior to 1/1/85 have been destroyed. Info taken from PCB facility files. Portions of the fac file show SCA Chemical as the generator.

**Warning Letter Comments:**

---

**Facility:** Elk River Municipal Utilities**Other Name:****EPA Assigned ID #:** 18825**Contact:** William Birrenkott**Address:** 322 King Avenue  
Elk River MN 55330**Phone:** 612-441-2020**Date Sent to Facility**

8/ 4/95

**Date Received by Facility**

8/ 7/95

**Date Response Received by EPA**

8/24/95

**Date of Letter**

**104(e) Response Comments:** Certificate of Destruction for HWM #0334 has the wrong number on it.

**Warning Letter Comments:**

---

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Ellis, City of  
**Other Name:**  
**EPA Assigned ID #:** 14825

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) LETTER INFO**

8/ 4/95  
8/ 7/95  
9/ 5/95  
8/31/95

**WARNING LETTER INFO**

**Contact:** Scott J. Miller  
**Address:** PO Box 27  
Ellis KS 67237  
**Phone:** 913-625-6919

**104(e) Response Comments:** The Ellis Municipal Power Plant is now owned by Midwest Energy, Inc.

**Warning Letter Comments:**

**Facility:** Empire District Electric Company  
**Other Name:**  
**EPA Assigned ID #:** 18875

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95  
8/ 7/95  
9/ 7/95  
9/ 6/95

**Contact:** Robert Hallman  
**Address:** PO Box 127  
Joplin MO 64802  
**Phone:**

**104(e) Response Comments:** 104(e) response contains list of capacitors but does not indicate what manifest they are associated with.

**Warning Letter Comments:**

**Facility:** Empire Electric Company  
**Other Name:**  
**EPA Assigned ID #:** 18900

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95

**Contact:** Alan or Irving Hasnass  
**Address:** 52100 1st Avenue  
Brooklyn NY 11232  
**Phone:**

**104(e) Response Comments:** No returned green card, no response, unable to locate PCB facility file. No equipment information has been entered into the database for this facility.

**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Environmental International Electric Servic  
**Other Name:**  
**EPA Assigned ID #:** 18925

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(c) LETTER INFO**

6/21/96

**WARNING LETTER INFO****Contact:**

**Address:** 1220 Wyoming  
Kansas City MO 64102

**Phone:**

**104(c) Response Comments:** 8/4/95 letter returned FOE. 6/21/96 letter sent to Wichita, KS returned "no such number." Information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** Environmental International Inc.  
**Other Name:**  
**EPA Assigned ID #:** 18950

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95

**Contact:** William McGaugh  
**Address:** 3126 Brinkerhoff Ro  
Kansas City KS 66115

**Phone:**

**104(c) Response Comments:** 8/4/95 letter returned - refused. Information taken from PCB facility files.

**Warning Letter Comments:**

**Facility:** Environmental International Inc. of Colorad  
**Other Name:**  
**EPA Assigned ID #:** 18975

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95

**Contact:** Jerry Wright Owner  
**Address:** Box 38155  
Denver CO 80238

**Phone:**

**104(c) Response Comments:** 8/4/95 letter returned FOE. Information taken from PCB facility files.

**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Essex Machine Works

**Other Name:**

**EPA Assigned ID #:** 19025

**Contact:** James G. Daolady, Pres.

**Address:** Box 7362  
Columbia MO 65025

**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned "attempted not known." Information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** Evansville Water & Light

**Other Name:**

**EPA Assigned ID #:** 19125

**Contact:** Merle Smith

**Address:** 31 S. Madison Street  
Evansville WI 53536

**Phone:** 608-882-2280

**104(e) Response Comments:** Generator has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** Fairfield Municipal Light Plant

**Other Name:**

**EPA Assigned ID #:** 19425

**Contact:**

**Address:** N.W. 6th Street  
Fairfield IL 62837

**Phone:**

**104(e) Response Comments:** No response received. Equipment information taken from PCB facility file.

**Warning Letter Comments:**

**104(c) LETTER INFO**

**Date Sent to Facility**

8/ 4/95

**Date Received by Facility**

**Date Response Received by EPA**

**Date of Letter**

**WARNING LETTER INFO**

127

**Date Sent to Facility**

8/ 4/95

**Date Received by Facility**

8/ 7/95

**Date Response Received by EPA**

10/31/95

**Date of Letter**

9/20/95

**Date Sent to Facility**

8/ 4/95

**Date Received by Facility**

8/ 7/95

**Date Response Received by EPA**

**Date of Letter**

2

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Fairhaven Electric Corporation  
**Other Name:**  
**EPA Assigned ID #:** 19450

**Contact:** Walter Looman  
**Address:** Fairhaven  
Fairhaven MN 55382  
**Phone:** 612-236-7800

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 8/28/95  
**Date of Letter** 8/24/95

**104(e) LETTER INFO****WARNING LETTER INFO**

**104(e) Response Comments:** Response states one capacitor was sent to PCB, the PCB invoice shows 1 Cap, however, the PCB Capacitor log shows 4 Cap were received.  
**Warning Letter Comments:**

**Facility:** Fairview Municipal Water & Light  
**Other Name:**  
**EPA Assigned ID #:** 19525

**Contact:**  
**Address:** 4192 Main  
Fairview OK 73737  
**Phone:**

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA**  
**Date of Letter**

5/21/96  
5/23/96

**104(e) Response Comments:** No response received. Information taken from PCB facility file.  
**Warning Letter Comments:**

**Facility:** Farrington Data Systems  
**Other Name:**  
**EPA Assigned ID #:** 19700

**Contact:** Antonette Dahmer  
**Address:** 3221 W. Big Beaver Rd., Sui  
Troy MI 48084  
**Phone:** 810-637-3020

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 8/22/95  
**Date of Letter** 8/16/95

**104(e) Response Comments:** Generator does not have any knowledge or documents pertaining to shipments made to PCB. Contractor unable to locate any PCB files for this facility.  
**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	Federal Mogul Corporation	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility		
EPA Assigned ID #:	19825	Date Response Received by EPA	9/11/95	
		Date of Letter	9/ 7/95	
Contact:	Nancy S. Martin			
Address:	PO Box 1966			
	Detroit MI 48235			
Phone:	810-354-8841			
104(e) Response Comments: Response includes information for the Target Products Division (34675).				
Warning Letter Comments:				
Facility:	Federated Rural Electric Association	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	19850	Date Response Received by EPA	9/ 5/95	
		Date of Letter	8/29/95	
Contact:	Richard G. Burud			
Address:	PO Box 69			
	Jackson MN 56143			
Phone:	507-847-3520			
104(e) Response Comments: Generator did not provide any information regarding HWM #3889. One response was received for all locations.				
Warning Letter Comments:				
Facility:	Fisher Cheese Company	Date Sent to Facility	6/21/96	
Other Name:		Date Received by Facility		
EPA Assigned ID #:	20100	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	615 W. Ervin Road			
	Van Wert OH 45891			
Phone:				
104(e) Response Comments: 8/4/95 letter returned FOE. 6/21/96 letter sent to Cleveland, OH returned FOE. Information taken from PCB facility file.				
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Flemming Electric Light Department  
**Other Name:**  
**EPA Assigned ID #:** 20200

**Contact:**  
**Address:** Flemming CO 80728  
**Phone:**

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) LETTER INFO**

8/ 4/95

**WARNING LETTER INFO**

**104(e) Response Comments:** No returned mail, no returned green card, no response. Information taken from PCB facility file.  
**Warning Letter Comments:**

**Facility:** Florida National Guard-Camp Bl  
**Other Name:**  
**EPA Assigned ID #:** 20225

**Contact:** Gene Cogdill  
**Address:** Box 465  
Starke FL 32091  
**Phone:**

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95

8/ 7/95

**104(e) Response Comments:** No response received. Information taken from PCB facility file.  
**Warning Letter Comments:**

**Facility:** Flying Tiger Line - Hanger #6  
**Other Name:**  
**EPA Assigned ID #:** 20275

**Contact:** Peter Cullen  
**Address:** JFK International A  
Jamaica NY 11430  
**Phone:**

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95

8/ 7/95

5/21/96

**104(e) Response Comments:**  
**Warning Letter Comments:** 5/21/96 warning letter returned "refused." Equipment information taken from PCB facility file.



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Foster Wheeler Corporation	Date Sent to Facility	6/21/96
Other Name:	(F.W. Environsponse Incorporated)	Date Received by Facility	6/24/96
EPA Assigned ID #:	20750	Date Response Received by EPA	8/ 2/96
		Date of Letter	7/29/96
Contact:	Elizabeth Maric-Moser		
Address:	Perryville Corporate Park		
	Clinton NJ 08809-4000		
Phone:	908-730-4000		
104(e) Response Comments: 8/4/95 letter returned FOE.			
Warning Letter Comments:			
Facility:	Frontier Chemical Waste Process	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	20625	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	4626 Royal Avenue		
	Niagara Fal NY 14303		
Phone:			
104(e) Response Comments: 8/4/95 letter returned FOE. Information taken from PCB facility file.			
Warning Letter Comments:			
Facility:	G.M. Electric Company	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	21825	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	Box 1694 214 Gertrude Ave		
	Grand Forks ND 58201		
Phone:			
104(e) Response Comments: 8/4/95 letter returned "attempted not known." Equipment information taken from PCB facility file.			
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Ganienkeh Indian Territory  
**Other Name:**  
**EPA Assigned ID #:** 20800

**Contact:** John Beauvais  
**Address:** PO Box 750  
 Kahnawake, QUE JoL1bo  
**Phone:** Unk

**104(c) Response Comments:** 8/4/95 letter returned "address unknown."

**Warning Letter Comments:**

**Facility:** Gardner Denver Compressors  
**Other Name:**  
**EPA Assigned ID #:** 20850

**Contact:** Leroy Willer  
**Address:** 1800 Garnder Expressway  
 Quincy IL 62301  
**Phone:** 217-222-5400

**104(e) Response Comments:** Includes information for Denver Gardner Machinery

**Warning Letter Comments:**

**Facility:** Garland, City of  
**Other Name:** (Garland Power & Light)  
**EPA Assigned ID #:** 20875

**Contact:** John Teel  
**Address:** PO Box 469002  
 Garland TX 75046-9002  
**Phone:** 214-205-3460

**104(e) Response Comments:** 8/4/95 letter returned "refused." Respondent was unable to locate any documents pertaining to shipments made to PCB. Information taken from PCB facility files.

**Warning Letter Comments:**

**104(c) LETTER INFO**

**WARNING LETTER INFO**

**Date Sent to Facility** 6/21/96  
**Date Received by Facility** 6/25/96  
**Date Response Received by EPA** 7/25/96  
**Date of Letter** 7/17/96

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 9/12/95  
**Date of Letter** 9/ 7/95

**Date Sent to Facility** 6/21/96  
**Date Received by Facility** 6/25/96  
**Date Response Received by EPA** 7/31/96  
**Date of Letter** 7/29/96

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Garnett Municipal Utility	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95
<b>EPA Assigned ID #:</b>	20925	<b>Date Response Received by EPA</b>	
		<b>Date of Letter</b>	
<b>Contact:</b>			
<b>Address:</b>	Box 120		
	Garnett IN 46738		
<b>Phone:</b>			
<b>104(e) Response Comments:</b>	No response received, no returned mail. Equipment information taken from PCB facility file.		
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	General Electric Company	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(RCA Record Division)	<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	31100	<b>Date Response Received by EPA</b>	8/12/96
		<b>Date of Letter</b>	8/ 9/96
<b>Contact:</b>	Teri R. Simon		
<b>Address:</b>	PO Box 1561		
	King of Prussia PA 19604		
<b>Phone:</b>	610-992-7970		
<b>104(e) Response Comments:</b>			
<b>Warning Letter Comments:</b>	GE has no information regarding shipments to PCB from this facility. Information taken from PCB facility file. Includes RCA-SSD (31150)		
<b>Facility:</b>	General Motors Corporation	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(Packard Electric Division G.M.)	<b>Date Received by Facility</b>	8/ 8/95
<b>EPA Assigned ID #:</b>	29750	<b>Date Response Received by EPA</b>	9/ 8/95
		<b>Date of Letter</b>	9/ 7/95
<b>Contact:</b>	Linda Bentley		
<b>Address:</b>	3044 W. Grand Blvd.		
	Detroit MI 48202-3220		
<b>Phone:</b>	313-556-2183		
<b>104(e) Response Comments:</b>	General Motors Corp. is responding for GMC Metal Fab Division, Mansfield Plant, GMC Delphi Packard Electric Systems Division, GMC NAO Powertrain Division.		
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	General Refractories Company	Date Sent to Facility	6/21/96
Other Name:		Date Received by Facility	6/24/96
EPA Assigned ID #:	21125	Date Response Received by EPA	8/19/96
		Date of Letter	8/16/96
Contact:			
Address:	600 Grant Street Pittsburgh PA 15219		
Phone:			
104(e) Response Comments:	8/4/95 letter not returned-no green card-no response. 6/21/96 FU letter sent to AP Green Refractories. Generator response to FOIA says that since no information says "AP Green Refractories" they are not liable. Info taken from PCB facility file.		
Warning Letter Comments:			
Facility:	General Tire, Inc.	Date Sent to Facility	8/ 4/95
Other Name:	(General Tire & Rubber Company)	Date Received by Facility	8/ 8/95
EPA Assigned ID #:	21150	Date Response Received by EPA	10/10/95
		Date of Letter	10/ 6/95
Contact:	Susan S. Gelfand		
Address:	One General Street Akron OH 44329-0001		
Phone:	216-798-2940		
104(e) Response Comments:	Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Information taken from the PCB facility file (red folder).		
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Geneva, City of	Date Sent to Facility	6/21/96
Other Name:	(Geneva Electric Department)	Date Received by Facility	6/24/96
EPA Assigned ID #:	21200	Date Response Received by EPA	6/27/96
		Date of Letter	6/25/96
Contact:	Hal E. Wright		
Address:	1800 South St. Geneva IL 60134		
Phone:	708-232-1501		
104(e) Response Comments:	8/4/95 letter returned "incorrect address."		
Warning Letter Comments:			
Facility:	Goldberger Foods	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	21325	Date Response Received by EPA	10/24/95
		Date of Letter	10/23/95
Contact:	Howard Goldberger		
Address:	11 West 28th Street Minneapolis MN 55408		
Phone:	612-872-6272		
104(e) Response Comments:	Response was received from GFI America, 2815 Blaisdell Ave. S., Minneapolis, MN 55408, 612-872-6262. Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Information was taken from the PCB facility file.		
Warning Letter Comments:			
Facility:	Golden Casting Corporation	Date Sent to Facility	8/ 4/95
Other Name:	(Golden Operations)	Date Received by Facility	8/ 7/95
EPA Assigned ID #:	21350	Date Response Received by EPA	8/28/95
		Date of Letter	8/23/95
Contact:	Alan R. Cronk		
Address:	1616 Tenth Street Columbus IN 47202		
Phone:	812-372-3701		
104(e) Response Comments:	Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Information taken from the PCB facility file (red folder).		
Warning Letter Comments:			
Prepared by Dynamac Corporation			
Comment.DBF/J 1/21/97			

Page 52

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Grand Island, City of	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	15000	<b>Date Response Received by EPA</b>	8/28/95
		<b>Date of Letter</b>	8/24/95
<b>Contact:</b>	Burhl Gilpin		
<b>Address:</b>	Box 1968		
	Grand Island NE 68802		
<b>Phone:</b>	308-385-5444		
<b>104(e) Response Comments:</b> Includes information for Phelps Control Center (30125)			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Grayson-Collin Electric Cooperative, Inc.	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	21525	<b>Date Response Received by EPA</b>	7/ 1/96
		<b>Date of Letter</b>	6/27/96
<b>Contact:</b>	Robert Cavender		
<b>Address:</b>	PO Box 548		
	Van Alstyne TX 75495-0548		
<b>Phone:</b>	903-482-5231		
<b>104(e) Response Comments:</b>			
<b>Warning Letter Comments:</b> Received letter dated 5/30/96 requesting extension until 6/30/96.			
<b>Facility:</b>	Greenwood Commission of Public	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	21700	<b>Date Response Received by EPA</b>	
		<b>Date of Letter</b>	
<b>Contact:</b>	Ray Dellinger		
<b>Address:</b>	Box 549		
	Greenwood SC 29648		
<b>Phone:</b>			
<b>104(e) Response Comments:</b> 8/4/95 letter returned "retired, return to sender." Equipment information taken from PCB facility file.			
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	HCMC	Date Sent to Facility	8/ 4/95
Other Name:	(Hennepin County Medical Center)	Date Received by Facility	8/ 7/95
EPA Assigned ID #:	22175	Date Response Received by EPA	9/ 7/95
		Date of Letter	9/ 5/95
Contact:	Daniel Wichman		
Address:	701 Park Avenue		
	Minneapolis MN 55415		
Phone:	612-347-3813		
104(e) Response Comments: Generator has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.			
Warning Letter Comments:			
Facility:	Hammermill Paper	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	21875	Date Response Received by EPA	9/15/95
		Date of Letter	9/14/95
Contact:	Steven J. Ginski		
Address:	1540 East Lake Road		
	Erie PA 16533		
Phone:	901-763-6000		
104(e) Response Comments: Hammermill Paper is a division of International Paper.			
Warning Letter Comments:			
Facility:	Hammond Valve Corp.	Date Sent to Facility	6/21/96
Other Name:		Date Received by Facility	6/24/96
EPA Assigned ID #:	21900	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	210 Tower Street		
	Prairie Dusec WI 53578		
Phone:			
104(e) Response Comments: No response received. Information taken from PCB facility file.			
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Hancock Field	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	21950	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	4789 ABG/DE Syracuse NY 13211		
Phone:			
104(e) Response Comments:	8/4/95 letter returned "insufficient address." Unable to locate PCB facility file. Equipment information taken from "Session" file.		
Warning Letter Comments:			
Facility:	Harris Tarkett	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 8/95
EPA Assigned ID #:	22000	Date Response Received by EPA	9/ 1/95
		Date of Letter	
Contact:	Joe H. Johns		
Address:	Box 300 Johnson City TN 37605		
Phone:	615-928-3122		
104(e) Response Comments:	Info. provided in 104(e) response is for shipment of transformers sent to American Industrial Waste. Database info. has been taken from PCB facility file for HWM #3625.		
Warning Letter Comments:			
Facility:	Hatfield, Borough of	Date Sent to Facility	8/ 4/95
Other Name:	(Hatfield Municipal Electric)	Date Received by Facility	8/ 7/95
EPA Assigned ID #:	22075	Date Response Received by EPA	8/21/95
		Date of Letter	8/15/95
Contact:	Mark Curfman		
Address:	401 South Main Street, PO B Hatfield PA 19440-0190		
Phone:	215-855-0781		
104(e) Response Comments:	Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Information taken from PCB facility file (redfolder).		
Warning Letter Comments:			



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Henry County REMC	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	22200	<b>Date Response Received by EPA</b>	9/ 8/95
		<b>Date of Letter</b>	9/ 6/95
<b>Contact:</b>	David Solida		
<b>Address:</b>	Box D		
	New Castle IN 47362-1046		
<b>Phone:</b>	317-529-1212		
<b>104(e) Response Comments:</b>	Unable to locate fac files for HWM 3620 and 3621. Analytical data is included in 104(e) response but the associated capacitor serial # does not match the serial # on the PCB capacitor log.		
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	High Voltage Maintenance	<b>Date Sent to Facility</b>	
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	22325	<b>Date Response Received by EPA</b>	
		<b>Date of Letter</b>	
<b>Contact:</b>			
<b>Address:</b>	1416 Sadalier Circl		
	Indianapoli IN 46239		
<b>Phone:</b>			
<b>104(e) Response Comments:</b>	Combined response with facility #22250		
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**104(e) LETTER INFO**

**WARNING LETTER INFO**

**Facility:** High Voltage Maintenance Corporation  
**Other Name:**  
**EPA Assigned ID #:** 22350

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**Contact:** Brenda Fogle and M  
**Address:** 1455 Jamike Avenue  
Erlanger KY 41018  
**Phone:**

**104(e) Response Comments:** Combined response with facility #22250  
**Warning Letter Comments:**

**Facility:** High Voltage Maintenance Corporation  
**Other Name:**  
**EPA Assigned ID #:** 22300

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**Contact:** Harry Peliska  
**Address:** 16285 West Lincoln  
New Berlin WI 53151  
**Phone:**

**104(e) Response Comments:** Combined response with facility #22250  
**Warning Letter Comments:**

**Facility:** High Voltage Maintenance Corporation  
**Other Name:**  
**EPA Assigned ID #:** 22275

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**Contact:**  
**Address:** 5100 Energy Drive  
Dayton OH 45414  
**Phone:**

**104(e) Response Comments:** Combined response with facility #22250  
**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** High Voltage Maintenance Corporation  
**Other Name:**  
**EPA Assigned ID #:** 22250

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) LETTER INFO**

8/ 4/95  
8/ 7/95  
9/ 8/95  
9/ 7/95

**WARNING LETTER INFO**

**Contact:**  
**Address:** 1455 Jamike Dr  
Erlanger KY 41018  
**Phone:** 606-371-5355

**104(e) Response Comments:** Unable to locate PCB facility files for HWM #2310, 2361, 2294, 3134, 3364, 3365. Info taken from 104(e) response. Generator did not provide information for HWM #0011 (Broker-SCA), 0676 (Broker-SCA), 0910 (Broker-SCA), and 1909. Info taken from PCB file

**Warning Letter Comments:**

**Facility:** Holdrege, City of  
**Other Name:** (Holdrege Municipal Power & Light)  
**EPA Assigned ID #:** 22475

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95  
8/7/95

**Contact:** Robert Meade  
**Address:** 502 Avenue  
Holdrege NE 68949  
**Phone:**

*Response received  
has no dates on it*

**104(e) Response Comments:** There are manifests in the 104(e) response without the manifest number.

**Warning Letter Comments:**

**Facility:** Holiday Inn  
**Other Name:**  
**EPA Assigned ID #:** 22500

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95

**Contact:** Ed McNeal  
**Address:** 1313 Nocholette Ave  
Minneapolis MN 55403  
**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned "attempted not known." Information taken from PCB facility file.

**Warning Letter Comments:**

*m*

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	Holy Cross Electric Association	Date Sent to Facility	6/21/96	
Other Name:		Date Received by Facility	6/22/96	
EPA Assigned ID #:	22550	Date Response Received by EPA	7/15/96	
		Date of Letter	7/10/96	
Contact:	Ted Jessup			
Address:	PO Drawer 2150 Glenwood Springs CO 81602			
Phone:	303-945-5491			
104(e) Response Comments: 8/4/95 letter returned "FOE." Unable to locate PCB facility file for this facility. Information taken from 104(e) response only.				
Warning Letter Comments:				
Facility:	Hood Electric	Date Sent to Facility	6/21/96	
Other Name:		Date Received by Facility	6/24/96	
EPA Assigned ID #:	22650	Date Response Received by EPA	8/ 5/96	
		Date of Letter	8/ 2/96	
Contact:	Terry Jenkins			
Address:	128 W. Rayen Ave Youngstown OH 44501			
Phone:	216-744-0255			
104(e) Response Comments: 8/4/96 letter returned "FOE."				
Warning Letter Comments:				
Facility:	Hudson-Rogers, AR	Date Sent to Facility	8/ 4/95	
Other Name:	(Land O'Lakes)	Date Received by Facility		
EPA Assigned ID #:	24750	Date Response Received by EPA	9/ 6/95	
		Date of Letter	9/ 5/95	
Contact:	John E. Starkey			
Address:	PO Box 777 Rogers AR 72756			
Phone:	501-636-1100			
104(e) Response Comments: Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Information taken from PCB facility file.				
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO	
Facility:	IDS Center-Limited Partnership	Date Sent to Facility	8/ 4/95		
Other Name:		Date Received by Facility	8/ 8/95		
EPA Assigned ID #:	22875	Date Response Received by EPA	10/ 2/95		
		Date of Letter	9/27/95		
Contact:					
Address:	80 S. 8th Street Su Minneapolis MN 55402				
Phone:					
104(e) Response Comments: Letter has received from building owner Heitman Properties, Ltd. They did not own the property during 1984-85 and have no information regarding shipments made to PCB. Equipment information was taken from PCB facility file.					
Warning Letter Comments:					
Facility:	Independence, City of	Date Sent to Facility	8/ 4/95		
Other Name:		Date Received by Facility	8/ 7/95		
EPA Assigned ID #:	15075	Date Response Received by EPA	9/ 6/95		
		Date of Letter	9/ 1/95		
Contact:	Dewayne E. Durst				
Address:	PO Box 1019 Independence MO 64051				
Phone:					
104(e) Response Comments: This is a combined response with Independence Power and Light					
Warning Letter Comments:					
Facility:	Indiana Michigan Power Company	Date Sent to Facility	8/ 4/95		
Other Name:	(Indiana & Michigan Electric Co.)	Date Received by Facility	8/ 8/95		
EPA Assigned ID #:	22975	Date Response Received by EPA	9/ 7/95		
		Date of Letter	9/ 5/95		
Contact:	Donald Baker				
Address:	PO Box 60 Ft. Wayne IN 46801				
Phone:	219-425-2118				
104(e) Response Comments: Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Information taken from the PCB facility file (red folder).					
Warning Letter Comments:					
Prepared by Dynamac Corporation					
Comment.DBF/J 1/21/97					
Page 60					

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Ingersoll Rand Corp.	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(Torrington Company)	<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	23050	<b>Date Response Received by EPA</b>	10/10/95
		<b>Date of Letter</b>	10/ 6/95
<b>Contact:</b>	James D. Ray		
<b>Address:</b>	942 Memorial Parkway Philipsburg NJ 08865		
<b>Phone:</b>	201-573-3102		
<b>104(e) Response Comments:</b> Generator has no knowledge or information pertaining to HWM #2355 and #2726. Information taken from "Session file". Response includes information from Torrington Co. (35150)			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Interstate Transformer Company, Inc.	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	23200	<b>Date Response Received by EPA</b>	9/ 7/95
		<b>Date of Letter</b>	8/31/95
<b>Contact:</b>	Nicholas Tirlea		
<b>Address:</b>	PO Box 11339 Lexington KY 40575-1339		
<b>Phone:</b>	502-863-1339		
<b>104(e) Response Comments:</b> Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Information taken from the PCB facility file. Generator accepted leaking PCB caps at the request of EPA and did not own the equipment. See 104(e) response.			
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** J L Shiely Company  
**Other Name:**  
**EPA Assigned ID #:** 23300

**Contact:** Todd Mittelstadt  
**Address:** 2915 Waters Road, Ste 105  
Eagan MN 55121  
**Phone:** 612-683-0600

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) LETTER INFO**

8/ 4/95  
8/ 7/95  
9/22/95  
9/21/95

**WARNING LETTER INFO**

**104(e) Response Comments:** Response includes info for all locations. The St. Cloud plant is now owned by Meridian Aggregates (HWM #3139).  
**Warning Letter Comments:**

**Facility:** Jefferson Electric  
**Other Name:**  
**EPA Assigned ID #:** 23600

**Contact:** Magnetech  
**Address:** 26 Century Blvd.  
Nashville TN 37229  
**Phone:**

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

6/21/96  
6/24/96

**104(e) Response Comments:** 8/4/95 letter sent to Bellwood, IL returned FOE. No response received. Equipment information taken from PCB facility file.  
**Warning Letter Comments:**

**Facility:** Jerry's Foods  
**Other Name:**  
**EPA Assigned ID #:** 23650

**Contact:**  
**Address:** 5125 S. Verona Aven  
Edina MN 55436  
**Phone:**

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95  
8/ 7/95

**104(e) Response Comments:** No response received. Information taken from PCB facility file.  
**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** Jerry's Super Value  
**Other Name:**  
**EPA Assigned ID #:** 23675

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

---

**104(e) LETTER INFO**

6/21/96  
6/24/96

---

**WARNING LETTER INFO**

**Contact:**  
**Address:** 3801 Shakopee Road  
Bloomington MN 55431  
**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned FOE. Information taken from PCB facility file.  
**Warning Letter Comments:**

---

**Facility:** Job Corps U.S. Department of Labor  
**Other Name:**  
**EPA Assigned ID #:** 23825

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95

**Contact:** Lavell Crismon/John F. Do  
**Address:** Highway 10  
Excelsior Springs MO 64024  
**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned refused. Equipment information taken from PCB facility file.  
**Warning Letter Comments:**

---

**Facility:** Joe Wheeler Electric Membership  
**Other Name:**  
**EPA Assigned ID #:** 23850

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95

**Contact:**  
**Address:** Box 889  
Hartselle AL 35640  
**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned FOE. Unable to locate PCB facility file. Information taken from "Session" file.  
**Warning Letter Comments:**

---



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	John Morrell & Company	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	23875	Date Response Received by EPA	10/10/95
		Date of Letter	10/ 6/95
Contact:	Larry Kinker		
Address:	1400 N. Weber		
	Sioux Falls SD 57101		
Phone:	513-579-6493		
104(e) Response Comments:		Letter dated 5/24/96 request change of counsel.	
Warning Letter Comments:			
Facility:	Johnson Division	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	23975	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	315 North Pierce		
	St. Paul MN 55104		
Phone:			
104(e) Response Comments:		8/4/95 letter returned "attempted not known." Equipment information taken from PCB facility file.	
Warning Letter Comments:			
Facility:	Joseph E. Seagram & Sons Incorporated	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	24000	Date Response Received by EPA	9/ 7/95
		Date of Letter	9/ 6/95
Contact:	John M. Kyle III, Esq.		
Address:	7 Ridge Avenue		
	Lawrencebur IN 47025		
Phone:	317-638-1313		
104(e) Response Comments:		Unable to locate PCB facility file for this generator.	
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Jump River Electric Cooperative	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	24025	<b>Date Response Received by EPA</b>	9/ 5/95
		<b>Date of Letter</b>	8/31/95
<b>Contact:</b>	Donald M. Lemke		
<b>Address:</b>	PO Box 99		
	Ladysmith WI 54848		
<b>Phone:</b>	715-532-5524		
<b>104(e) Response Comments:</b>			
<b>Warning Letter Comments:</b> Generator claims that information regarding shipments made to PCB are included in the Dairyland Power Coop response (16825). Unable to locate any information in the Dairyland response regarding Jump River Electric.			
<b>Facility:</b>	Kahoka Light & Water Department	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	24075	<b>Date Response Received by EPA</b>	6/17/96
		<b>Date of Letter</b>	6/10/96
<b>Contact:</b>	Robert Killday		
<b>Address:</b>	1910 E. McPherson		
	Kirkville MO 63501		
<b>Phone:</b>			
<b>104(e) Response Comments:</b>			
<b>Warning Letter Comments:</b> Response was received in envelope from Soyland Power Coop. No mention was made in 104(e) regarding any name change.			
<b>Facility:</b>	Kain Electric Incorporated	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	24100	<b>Date Response Received by EPA</b>	
		<b>Date of Letter</b>	
<b>Contact:</b>	Janice D. Chenowet		
<b>Address:</b>	610 NW 2nd Street		
	Richmond IN 47374		
<b>Phone:</b>			
<b>104(e) Response Comments:</b> 8/4/95 letter returned "addressee unknown." 6/21/96 FU letter was sent to Kain Electric c/o Thor Electric. Respondent has no knowledge of Kain Electric or shipments made to PCB. Information taken from PCB facility file.			
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Kascuisk County REMC	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	24200	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	523 S. Buffalo Warsaw IN 46580		Same as Kosciusko REMC.
Phone:			This facility is a misspelling.
104(e) Response Comments:	No response received. Information taken from PCB facility file.		
Warning Letter Comments:			
Facility:	Kaufman County Electric Coop	Date Sent to Facility	6/21/96
Other Name:		Date Received by Facility	6/25/96
EPA Assigned ID #:	24225	Date Response Received by EPA	7/24/96
		Date of Letter	7/18/96
Contact:	John Hodge		
Address:	1800 Highway 243 East Kaufman TX 75142		
Phone:	214-932-2214		
104(e) Response Comments:	8/4/95 letter returned FOE.		
Warning Letter Comments:			
Facility:	Kingfisher Municipal Light Department	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	24400	Date Response Received by EPA	
		Date of Letter	
Contact:	Carl Williams		
Address:	301 North Main Box Kingfisher OK 73750		
Phone:			
104(e) Response Comments:	No response received. Information taken from PCB facility file.		
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Kit Carson Electric	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	24450	<b>Date Response Received by EPA</b>	11/ 7/95
		<b>Date of Letter</b>	11/ 2/95
<b>Contact:</b>	Luis A. Reyes		
<b>Address:</b>	Box 587		
	Taos NM 87571		
<b>Phone:</b>	800-688-6780		
<b>104(e) Response Comments:</b> Generator does not have hay knowledge or documents pertaining to shipments sent to PCB. Information taken from the PCB facility file.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Kravco Company	<b>Date Sent to Facility</b>	6/21/96
<b>Other Name:</b>	(Krazco Company)	<b>Date Received by Facility</b>	6/25/96
<b>EPA Assigned ID #:</b>	24625	<b>Date Response Received by EPA</b>	8/29/96
		<b>Date of Letter</b>	8/26/96
<b>Contact:</b>	Ralph Siskind		
<b>Address:</b>	234 Mall Blvd.		
	King of Prussia PA 19406		
<b>Phone:</b>	Unk		
<b>104(e) Response Comments:</b> 8/4/96 letter returned "attempted unknown."			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	L.T.V. Aerospace & Defense	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	5/21/96
<b>EPA Assigned ID #:</b>	25600	<b>Date Response Received by EPA</b>	8/ 8/95
		<b>Date of Letter</b>	
<b>Contact:</b>			
<b>Address:</b>	9314 W. Jefferson		
	Grand Priarie TX 75051		
<b>Phone:</b>			
<b>104(e) Response Comments:</b> No response received in response to 8/4/95 information request.			
<b>Warning Letter Comments:</b> Warning letter sent to Carswell AFB returned "No such address". Letter received from Northrop Grumman (8/18/96) request resend to LTV Law Department, Cleveland Ohio. Equipment information taken from PCB facility file.			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	LTV Steel	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	25500	<b>Date Response Received by EPA</b>	10/27/95	
		<b>Date of Letter</b>	10/25/95	
<b>Contact:</b>	Thaddeus A. Zalenski			
<b>Address:</b>	PO Box 847 Hoyt Lake s MN 55750			
<b>Phone:</b>	216-622-5000			
<b>104(e) Response Comments:</b> Generator was not able to locate any document pertaining to shipments sent to PCB. Info. taken from the PCB facility file (red folder).				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Laidlaw Environmental Services, Inc.	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>	(Triangle Resource Industries)	<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	35350	<b>Date Response Received by EPA</b>	9/ 7/95	
		<b>Date of Letter</b>	9/ 5/95	
<b>Contact:</b>	Barbara Hamilton			
<b>Address:</b>	PO Box 210799 Columbia SC 29221			
<b>Phone:</b>	803-798-2993			
<b>104(e) Response Comments:</b> Generator did not provide any info regarding #0798 for facility located in Reidsville, NC. Info taken from facility file.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Lake County Government	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95	
<b>EPA Assigned ID #:</b>	24650	<b>Date Response Received by EPA</b>	8/30/95	
		<b>Date of Letter</b>	8/28/95	
<b>Contact:</b>	John S. Dull, City Attorney			
<b>Address:</b>	2293 North Main Crown Point IN 46307			
<b>Phone:</b>	755-3058			
<b>104(e) Response Comments:</b> Generator has no knowledge of any shipments made to PCB.				
<b>Warning Letter Comments:</b>				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Landy Packing Company	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	24775	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	606 South 25th Aven St. Cloud MN 56301		
Phone:			
104(e) Response Comments: 8/4/95 letter sent to incorrect address. Letter was opened in error. No response received. Information taken from PCB facility file.			
Warning Letter Comments:			
Facility:	Langford Electric Company	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	24800	Date Response Received by EPA	9/22/95
		Date of Letter	9/20/95
Contact:	Cindy L. Davis		
Address:	918 W. Lake Street Minneapolis MN 55402-3788		
Phone:	612-338-0661		
104(e) Response Comments: Generator is not able to locate any documents pertaining to shipments sent to PCB. Info. taken from PCB facility file (red folder).			
Warning Letter Comments:			
Facility:	Lea Foods	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 8/95
EPA Assigned ID #:	24875	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	702 13th Street Albert Lea MN 56007		
Phone:			
104(e) Response Comments: No response received. Information taken from PCB facility file.			
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

<b>GENERAL INFORMATION</b>		<b>104(e) LETTER INFO</b>	<b>WARNING LETTER INFO</b>
<b>Facility:</b>	Lincoln Elementary School	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95
<b>EPA Assigned ID #:</b>	25125	<b>Date Response Received by EPA</b>	11/ 9/95
		<b>Date of Letter</b>	11/ 6/95
<b>Contact:</b>	Kerry Leider		
<b>Address:</b>	215 NW First Ave East Duluth MN 55802		
<b>Phone:</b>	Unknown		
<b>104(e) Response Comments:</b>	Response received from Independent School District #709. Direct future correspondence to Kerry Leider, ISD #709, 215 NW First Avenue E, Duluth, MN 55802. Response includes information for Ordean Jr. High (29475)		
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Lincroft Enterprises	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	25175	<b>Date Response Received by EPA</b>	1/ 7/95
		<b>Date of Letter</b>	
<b>Contact:</b>	Harry Stadler		
<b>Address:</b>	90 Woodbridge Ctr Dr., Ste 6 Woodbridge NJ 07095		
<b>Phone:</b>	908-750-1111		
<b>104(e) Response Comments:</b>	Generator has no knowledge or information regarding shipments made to PCB. Info taken from PCB facility file. Please see facility file for conflicting info re: pcb concentrations.		
<b>Warning Letter Comments:</b>	Warning letter was sent to generator in error.		

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Line Construction Company, Inc.	Date Sent to Facility	6/21/96
Other Name:		Date Received by Facility	6/24/96
EPA Assigned ID #:	25200	Date Response Received by EPA	7/ 9/96
		Date of Letter	6/28/96
Contact:	Margaret Fessler		
Address:	4200 Somerset Dr., #260		
	Prairie Village KS 66208		
Phone:	913-341-1212		
104(e) Response Comments:	8/4/95 letter returned FOE. Respondent has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.		
Warning Letter Comments:			
Facility:	Louis Padnos Iron and Metal Company	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	25400	Date Response Received by EPA	12/22/95
		Date of Letter	12/18/95
Contact:	Shelley E. Padnos		
Address:	PO Box 1979		
	Holland MI 49422-1979		
Phone:	616-396-6521		
104(e) Response Comments:	Generator did not provide any information regarding HWM #1496. The fac file only contains COD dated 03/25/85 and a note that more info. can be located under Delta Star.		
Warning Letter Comments:			



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	Lyon-Lincoln Electric Cooperative, Inc.	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	25575	<b>Date Response Received by EPA</b>	9/27/95	
		<b>Date of Letter</b>	9/22/95	
<b>Contact:</b>	Michael Buckle			
<b>Address:</b>	Box 639			
	Tyler MN 56178-0639			
<b>Phone:</b>	507-247-5505			
<b>104(e) Response Comments:</b> Generator did not provide info. regarding HWM #0568, #0111, #2303. Analytical info. from Preventive Chemical Behavior is included with response. It is unclear what HWM this info. applies to.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	MagneTek Ohio Transformer Corporation	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>	(Ohio Transformer)	<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	29275	<b>Date Response Received by EPA</b>	10/ 4/95	
		<b>Date of Letter</b>	10/ 3/95	
<b>Contact:</b>	Donald J. Pyles			
<b>Address:</b>	Box 21300			
	Canton OH 44701			
<b>Phone:</b>	216-453-2118			
<b>104(e) Response Comments:</b> PCB facility file for HWM #3414 shows that the date received and the disposal date are both 10/18/85.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Mahaska, City of	<b>Date Sent to Facility</b>	8/ 4/95	5/21/96
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	5/23/96
<b>EPA Assigned ID #:</b>	15150	<b>Date Response Received by EPA</b>		8/ 6/96
		<b>Date of Letter</b>		7/10/96
<b>Contact:</b>	Mayor Roger Lambert			
<b>Address:</b>	PO Box 92			
	Mahaska KS 66955			
<b>Phone:</b>	Unk			
<b>104(e) Response Comments:</b> Generator has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.				
<b>Warning Letter Comments:</b>				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** Marathon Oil Company

**Other Name:**

**EPA Assigned ID #:** 25825

**Contact:** Ronald L. Andes

**Address:** 539 S. Main St.  
Findlay OH 45840

**Phone:** 419-422-2121

**Date Sent to Facility**

**Date Received by Facility**

**Date Response Received by EPA**

**Date of Letter**

---

**104(e) LETTER INFO**

8/ 4/95

8/ 7/95

9/21/95

9/18/95

---

**WARNING LETTER INFO**

**104(e) Response Comments:** Followup 104(e) info req was sent in error. Second response was received from Candance Young on 7/22/96 claiming that they had no knowledge or information regarding equipment sent to PCB

**Warning Letter Comments:**

---

**Facility:** Marion, City of

**Other Name:** (Marion Municipal Power Dept.)

**EPA Assigned ID #:** 25875

**Contact:** Joan Bowers

**Address:** 203 N. 3rd St.  
Marion KS 66861

**Phone:** 316-382-3703

**Date Sent to Facility**

**Date Received by Facility**

**Date Response Received by EPA**

**Date of Letter**

8/ 4/95

10/16/95

9/13/95

9/12/95

**104(e) Response Comments:** Generator does not have any knowledge or documents pertaining to shipments sent to PCB. Information taken from the PCB facility file (red folder).

**Warning Letter Comments:**

---

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	Marlow, City of	<b>Date Sent to Facility</b>	8/ 4/95	5/21/96
<b>Other Name:</b>	(Marlo Electric Dept)	<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	25950	<b>Date Response Received by EPA</b>		6/10/96
		<b>Date of Letter</b>		6/ 6/96
<b>Contact:</b>	Benny McLearen			
<b>Address:</b>	PO Box 113			
	Marlo OK 73055			
<b>Phone:</b>	658-5401			
<b>104(e) Response Comments:</b>				
<b>Warning Letter Comments:</b> Generator submitted information for 2 transformers sent to Aptus, Inc. Capacitor information was taken from PCB facility file.				
<b>Facility:</b>	Martin Marietta Aluminum	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 9/95	
<b>EPA Assigned ID #:</b>	26025	<b>Date Response Received by EPA</b>	10/ 6/95	
		<b>Date of Letter</b>	10/ 4/95	
<b>Contact:</b>	Paul Sebok			
<b>Address:</b>	1515 W. 190th St., #455			
	Gardena CA 90948			
<b>Phone:</b>	310-352-3362			
<b>104(e) Response Comments:</b> Unable to locate facility files.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Martin Marietta Corporation	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>	(General Electric/Syracuse, NY)	<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	21050	<b>Date Response Received by EPA</b>	10/31/95	
		<b>Date of Letter</b>	10/ 5/95	
<b>Contact:</b>	Brian A. Kent			
<b>Address:</b>	PO Box 4840			
	Syracuse NY 13221-4840			
<b>Phone:</b>	315-456-6976			
<b>104(e) Response Comments:</b> Per 104(e) response, effective 04/02/93, General Elect. transferred its aerospace business to Martin Marietta which included GE owned and/or operated in Syracuse, NY.				
<b>Warning Letter Comments:</b>				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Martin Marietta Corporation	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(RCA Corporation)	<b>Date Received by Facility</b>	8/10/95
<b>EPA Assigned ID #:</b>	31075	<b>Date Response Received by EPA</b>	10/11/95
		<b>Date of Letter</b>	10/ 5/95
<b>Contact:</b>	Kenneth Hofbauer		
<b>Address:</b>	1 Federal Street Camden NJ 08102		
<b>Phone:</b>	609-338-4745		
<b>104(e) Response Comments:</b>	RCA Corporation merged into GE 12/31/87. Effective 04/02/93, GE transferred its aerospace business to Martin Marietta. Unable to locate PCB facility file for HWM #3065.		
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Martin Marietta Materials	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	26000	<b>Date Response Received by EPA</b>	10/ 6/95
		<b>Date of Letter</b>	10/ 4/95
<b>Contact:</b>	Yvonne C. Bailey		
<b>Address:</b>	2710 Wycliff Rd. Raleigh NC 27607		
<b>Phone:</b>	919-783-4655		
<b>104(e) Response Comments:</b>	104(e) response did not include information regarding HWM #1284. Information taken from PCB facility file.		
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Martin Marietta/Wedron Facility	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	25975	<b>Date Response Received by EPA</b>	10/ 6/95
		<b>Date of Letter</b>	10/ 5/95
<b>Contact:</b>	James DeNapoli		
<b>Address:</b>	West Olive Street Wedron IL 60557		
<b>Phone:</b>	303-971-1905		
<b>104(e) Response Comments:</b>	Response was received from Lockheed Martin Corporation. Facility purchased by Fairmount Minerals in 1984. See response for more info.		
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	Martinsville, City of	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	15175	<b>Date Response Received by EPA</b>	9/ 5/95	
		<b>Date of Letter</b>	8/30/95	
<b>Contact:</b>	Eugene C. Richardson			
<b>Address:</b>	55 W. Church, Box 1112			
	Martinsville VA 24112			
<b>Phone:</b>	540-656-5183			
<b>104(e) Response Comments:</b> Generator did not provide copies of HWM. Unable to locate facility file for HWM #0422, #0857, and #3182.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	McPherson-Board of Public, City of	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	15200	<b>Date Response Received by EPA</b>	10/10/95	
		<b>Date of Letter</b>	10/ 5/95	
<b>Contact:</b>	R.N. Anderson			
<b>Address:</b>	PO Box 1008			
	McPherson KS 67460			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> Generator would be interested in considering a de micromis proposal.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Memorial Hospital	<b>Date Sent to Facility</b>	8/ 4/95	5/21/96
<b>Other Name:</b>	(Memorial Hospital at Easton MD)	<b>Date Received by Facility</b>	8/ 7/95	5/23/96
<b>EPA Assigned ID #:</b>	26375	<b>Date Response Received by EPA</b>		6/ 3/96
		<b>Date of Letter</b>		6/ 6/96
<b>Contact:</b>	Robert Bradford			
<b>Address:</b>	219 S. Washington St.			
	Easton MD 21601			
<b>Phone:</b>	410-822-1000			
<b>104(e) Response Comments:</b>				
<b>Warning Letter Comments:</b> Generator claims that they have never disposed of anything at PCB. Information taken from PCB facility file.				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	Metal Masters Food Service Equipment Co	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95	
<b>EPA Assigned ID #:</b>	26525	<b>Date Response Received by EPA</b>	8/24/95	
		<b>Date of Letter</b>	8/21/95	
<b>Contact:</b>	John C. Andrade, Attorney			
<b>Address:</b>	655 Glenwood Avenue Smyrna DE 19977			
<b>Phone:</b>	302-678-3262			
<b>104(e) Response Comments:</b> Generator does ot have any knowledge or documents pertaining to shipments sent to PCB. Info taken from PCB facility files.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Meyer Electric	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95	
<b>EPA Assigned ID #:</b>	26575	<b>Date Response Received by EPA</b>	8/28/95	
		<b>Date of Letter</b>	8/22/95	
<b>Contact:</b>				
<b>Address:</b>	308 E. Main Melrose MN 56352			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> Letter received from Darlene Ostendorf advises that the owners responsible for shipment of equipment to PCB are deceased. Information taken from PCB facility file.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Michigan Department of Natural Resources	<b>Date Sent to Facility</b>	8/ 4/95	5/21/96
<b>Other Name:</b>	(State of Michigan DNR)	<b>Date Received by Facility</b>	8/ 8/95	
<b>EPA Assigned ID #:</b>	33600	<b>Date Response Received by EPA</b>		
		<b>Date of Letter</b>		
<b>Contact:</b>	Dept. of Environmental Qu			
<b>Address:</b>	38980 7 Mile Road Livonia MI 48125			
<b>Phone:</b>	313-953-0241			
<b>104(e) Response Comments:</b>				
<b>Warning Letter Comments:</b> Warning letter returned "attempted not known." 8/4/95 letter was sent to the same address and received. No response. Equipment information taken from PCB facility file.				

***PCB Treatment, Inc. General Information***  
***Review of Facilities Requiring Follow-up and Warning Letters***

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	MidAmerica Energy	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>	(Sherrard Power System)	<b>Date Received by Facility</b>	8/11/95	
<b>EPA Assigned ID #:</b>	32475	<b>Date Response Received by EPA</b>	10/10/95	
		<b>Date of Letter</b>	10/ 5/95	
<b>Contact:</b>	Cathy S. Woollums			
<b>Address:</b>	106 E. 2nd Street			
	Davenport IA 52808-4350			
<b>Phone:</b>	319-333-8009			
<b>104(e) Response Comments:</b> Unable to locate PCB files for HWM #1482.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Midwest Electric Cooperative	<b>Date Sent to Facility</b>	6/21/96	
<b>Other Name:</b>		<b>Date Received by Facility</b>	6/24/96	
<b>EPA Assigned ID #:</b>	26650	<b>Date Response Received by EPA</b>	8/16/96	
		<b>Date of Letter</b>	8/14/96	
<b>Contact:</b>	Edwin Jackson			
<b>Address:</b>	PO Box 518			
	Roby TX 79549			
<b>Phone:</b>	Unk			
<b>104(e) Response Comments:</b> 8/4/95 letter returned FOE.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Milltown Electric	<b>Date Sent to Facility</b>	8/ 4/95	5/21/96
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	5/23/96
<b>EPA Assigned ID #:</b>	26775	<b>Date Response Received by EPA</b>		
		<b>Date of Letter</b>		
<b>Contact:</b>	Jack Whitman			
<b>Address:</b>	39 Washington Avenue			
	Milltown NJ 08850			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> No response received. Information taken from PCB facility file.				
<b>Warning Letter Comments:</b>				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Minneapolis Public School  
**Other Name:** (Franklin Junior High)  
**EPA Assigned ID #:** 20475

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) LETTER INFO**

8/ 4/95

8/ 7/95

8/31/95  
8/29/95

**WARNING LETTER INFO**

5/21/96

5/24/96

**Contact:**

**Address:** 1501 Aldrich Avenue  
Minneapolis MN 55411

**Phone:**

**104(e) Response Comments:** No response received. Information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** Minneapolis Public School  
**Other Name:** (Loring Elementary)  
**EPA Assigned ID #:** 25350

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95

8/ 7/95

8/31/95

8/29/95

**Contact:**

**Address:** Ken Meyer  
807 NE Broadway  
Minneapolis MN 55413-2398

**Phone:** 612-627-2082

**104(e) Response Comments:** Generator has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** Minneapolis Public School  
**Other Name:** (Lehmann Center)  
**EPA Assigned ID #:** 24925

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95

8/ 7/95

8/31/95

8/29/95

**Contact:**

**Address:** Ken Meyer  
807 NE Broadway  
Minneapolis MN 55408

**Phone:** 612-627-8028

**104(e) Response Comments:** Generator has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.

**Warning Letter Comments:**



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

<b>GENERAL INFORMATION</b>		<b>104(e) LETTER INFO</b>	<b>WARNING LETTER INFO</b>
<b>Facility:</b>	Minneapolis Public School	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(Nutrition Center)	<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	29050	<b>Date Response Received by EPA</b>	8/31/95
		<b>Date of Letter</b>	8/29/95
<b>Contact:</b>	Ken Meyer		
<b>Address:</b>	807 NE Broadway		
	Minneapolis MN 55413-2398		
<b>Phone:</b>	612-627-2082		
<b>104(e) Response Comments:</b> Generator has no knowledge or information regarding shipments make to PCB. Information taken from PCB facility file.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Minneapolis Public Schools	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(North High School)	<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	28475	<b>Date Response Received by EPA</b>	9/ 5/95
		<b>Date of Letter</b>	8/30/95
<b>Contact:</b>	Ken Meyer		
<b>Address:</b>	807 Northeast Broadway		
	Minneapolis MN 55413-2398		
<b>Phone:</b>			
<b>104(e) Response Comments:</b> Generator has no knowledge or information regarding shipments to PCB. Information taken from PCB facility file.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Minnkota Power Cooperative, Incorporated	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 5/95
<b>EPA Assigned ID #:</b>	26875	<b>Date Response Received by EPA</b>	9/11/95
		<b>Date of Letter</b>	9/ 7/95
<b>Contact:</b>	Loren L. Johnson		
<b>Address:</b>	P.O. Box 13200		
	Grand Forks ND 58203-3200		
<b>Phone:</b>	701-795-4000		
<b>104(e) Response Comments:</b> Analytical results are included in the response, however, it is unclear what equipment the results are for.			
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

<b>GENERAL INFORMATION</b>		<b>104(e) LETTER INFO</b>	<b>WARNING LETTER INFO</b>
<b>Facility:</b>	Mirro of Manitowoc	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(Mirro Corporation)	<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	26900	<b>Date Response Received by EPA</b>	8/17/95
		<b>Date of Letter</b>	8/15/95
<b>Contact:</b>	Peter J. Schult		
<b>Address:</b>	4000 Auburn St. Rockford IL 61101		
<b>Phone:</b>	815-969-6151		
<b>104(e) Response Comments:</b>		Newell owns Mirro and is answering on this response.	
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Modesto Irrigation District	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95
<b>EPA Assigned ID #:</b>	27000	<b>Date Response Received by EPA</b>	8/21/95
		<b>Date of Letter</b>	8/17/95
<b>Contact:</b>	M.G. Nelson		
<b>Address:</b>	1231 11th Street Modesto CA 95352-4060		
<b>Phone:</b>	209-526-7352		
<b>104(e) Response Comments:</b>		HWM #0954 for Modesto is part of the North American Environmental file.	
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Mohave Electric Cooperative	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95
<b>EPA Assigned ID #:</b>	27025	<b>Date Response Received by EPA</b>	10/ 4/95
		<b>Date of Letter</b>	9/29/95
<b>Contact:</b>	Robert E. Broz		
<b>Address:</b>	Box 1045 Bull Head City AZ 86430		
<b>Phone:</b>	520-763-4115		
<b>104(e) Response Comments:</b>		PRP's response contained no specific equipment info. PRP stated that they never sent equipment to PCB.	
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Mohawk Municipal Commission	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	27050	Date Response Received by EPA	9/ 5/95
		Date of Letter	8/28/95
Contact:	William Buddenhagen		
Address:	28 Columbia Street		
	Mohawk NY 13407		
Phone:	315-866-4170		
104(e) Response Comments: Unable to locate PCB facility file for HWM #314150. Information taken from 104(e).			
Warning Letter Comments:			
Facility:	Monona County REC	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	27075	Date Response Received by EPA	5/21/96
		Date of Letter	5/23/96
Contact:	Keith Crawford		
Address:	PO Box 359		
	Onawa IA 51040-0359		
Phone:	712-423-1622		
104(e) Response Comments:			
Warning Letter Comments: Generator returned copy of response dated 9/1/95. That letter was not received by EPA.			
Facility:	Monroe City, City of	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	15250	Date Response Received by EPA	5/21/96
		Date of Letter	5/23/96
Contact:			
Address:	300 North Main		
	Monroe City MO 63456		
Phone:			
104(e) Response Comments: No response received. Information taken from PCB facility file.			
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Monroe County Electric Cooperative	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	27100	Date Response Received by EPA	9/ 5/95
		Date of Letter	8/29/95
Contact:	Joseph J. Fellin		
Address:	901 North Market		
	Waterloo IL 62298		
Phone:	618-939-7171		
104(e) Response Comments:		Unable to locate fac file for HWM #0504.	
Warning Letter Comments:			
Facility:	Morrison Knudson Corporation	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	27175	Date Response Received by EPA	9/15/95
		Date of Letter	9/12/95
Contact:	Jan K. Horbaczewski		
Address:	P.O. Box 400090		
	San Antonio TX 78229		
Phone:	210-244-4689		
104(e) Response Comments:		Generator did not respond for HWM #1280 and #1034.	
Warning Letter Comments:			
Facility:	Municipal Light & Power	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	27425	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:			
	Westbrook MN 56138		
Phone:			
104(e) Response Comments:		No returned mail, no returned green card, no response. Equipment information taken from PCB facility file.	
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO	
Facility:	Municipal Power & Light	Date Sent to Facility	8/ 4/95	5/21/96
Other Name:		Date Received by Facility	8/ 7/95	5/23/96
EPA Assigned ID #:	27450	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	Box 592			
	Coleman TX 76834			
Phone:				
104(e) Response Comments:	No response received. Information taken from PCB facility file.			
Warning Letter Comments:				
Facility:	Municipal Power & Light	Date Sent to Facility	8/ 4/95	
Other Name:	(Henderson Municipal Light & Power)	Date Received by Facility	8/ 8/95	
EPA Assigned ID #:	22100	Date Response Received by EPA	9/ 7/95	
		Date of Letter	9/ 5/95	
Contact:	Kendel Bryan			
Address:	100 Fifth Street			
	Henderson KY 42420			
Phone:	502-826-2726			
104(e) Response Comments:	Unable to locate PCB facility file for HWM #2607.			
Warning Letter Comments:				
Facility:	N.V.F. Company	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 8/95	
EPA Assigned ID #:	29075	Date Response Received by EPA	10/10/95	
		Date of Letter	10/ 5/95	
Contact:	Harley N. Trice			
Address:	204 Gale Lane, P.O. Box 390			
	Kennett Square PA 19348			
Phone:	412-288-3282			
104(e) Response Comments:	NVF Company is currently in bankruptcy.			
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

<b>GENERAL INFORMATION</b>	<b>104(e) LETTER INFO</b>	<b>WARNING LETTER INFO</b>
<b>Facility:</b> NOVEC	<b>Date Sent to Facility</b> 8/ 4/95	
<b>Other Name:</b> (Northern Virginia EMC)	<b>Date Received by Facility</b> 8/ 8/95	
<b>EPA Assigned ID #:</b> 28775	<b>Date Response Received by EPA</b> 9/ 8/95	
	<b>Date of Letter</b> 8/31/95	
<b>Contact:</b> Larry Gunnells		
<b>Address:</b> 10323 Lomond Dr.		
Manassa VA 22110		
<b>Phone:</b> 703-335-0572		

**104(e) Response Comments:** Generator did not include information for HWM #1106. Information taken from PCB facility file.

**Warning Letter Comments:**

<b>Facility:</b> National Alumunim & Brass Foundry, Inc.	<b>Date Sent to Facility</b> 8/ 4/95	
<b>Other Name:</b>	<b>Date Received by Facility</b> 8/ 7/95	
<b>EPA Assigned ID #:</b> 27575	<b>Date Response Received by EPA</b> 8/15/95	
	<b>Date of Letter</b> 8/15/95	
<b>Contact:</b> Robert Fenton, Pres.		
<b>Address:</b> PO Box 290		
Independenc MO 64051		
<b>Phone:</b> 816-833-4500		

**104(e) Response Comments:** Owner is deceased.



**Warning Letter Comments:**

<b>Facility:</b> New Era Electric	<b>Date Sent to Facility</b> 8/ 4/95	5/21/96
<b>Other Name:</b>	<b>Date Received by Facility</b> 8/ 8/95	5/23/96
<b>EPA Assigned ID #:</b> 27875	<b>Date Response Received by EPA</b>	6/21/96
	<b>Date of Letter</b>	6/20/96
<b>Contact:</b> Gary Hurse		
<b>Address:</b> Box 1270		
Athens TX 75751		
<b>Phone:</b> 903-675-5688		

**104(e) Response Comments:**

**Warning Letter Comments:** Generator provided information for equipment sent to ENSCO, Inc. Information taken from PCB facility file.

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	New Ulm Utilities	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	27975	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	New Ulm MN 56073			
Phone:				
104(e) Response Comments:	Fax received from generator dated 9/11/95 acknowledges extension to 10/6/95. No response received. Equipment information taken from PCB facility file.			
Warning Letter Comments:				
Facility:	New York State Dept of Env Conservation	Date Sent to Facility	8/ 4/95	
Other Name:	(N.Y.S. Dept. of Environmental)	Date Received by Facility	8/ 8/95	
EPA Assigned ID #:	29100	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	S.U.N.Y. Building # Stony Brook NY 11794			
Phone:				
104(e) Response Comments:	No response received. Equipment information taken from PCB facility file.			
Warning Letter Comments:				
Facility:	New York State Electric & Gas	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	28000	Date Response Received by EPA	10/ 5/95	
		Date of Letter	10/ 3/95	
Contact:	Joseph M. Simone			
Address:	PO Box 5224 Binghamton NY 13902			
Phone:	607-762-7498			
104(e) Response Comments:	RCRA ID: NYD013508916, NYD079692117, NYD000730473, NYD000730366, NYD980763700, NYD000730358 - Resp for all facilities.			
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO	
Facility:	Niles Water & Light	Date Sent to Facility	8/ 4/95	5/21/96
Other Name:		Date Received by Facility	8/ 7/95	6/23/96
EPA Assigned ID #:	28150	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	34 West State St. Niles OH 44446			
Phone:				
104(e) Response Comments:	No response received. Information taken from PCB facility file.			
Warning Letter Comments:				
Facility:	North American Environmental Inc.	Date Sent to Facility	6/21/96	
Other Name:		Date Received by Facility	6/24/96	
EPA Assigned ID #:	28350	Date Response Received by EPA		
		Date of Letter		
Contact:	Leonard Smith, Reg. Agen			
Address:	2770 S. Maryland Pkwy, #50 Las Vegas NV 89109			
Phone:				
104(e) Response Comments:	8/4/95 letter returned FOE. No response received. Equipment information taken from PCB facility file.			
Warning Letter Comments:				
Facility:	North Star School	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	28550	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	2400 Girard Minneapolis MN 55411			
Phone:				
104(e) Response Comments:	No response received. Information taken from PCB facility file.			
Warning Letter Comments:				



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

<b>GENERAL INFORMATION</b>		<b>104(e) LETTER INFO</b>		<b>WARNING LETTER INFO</b>
<b>Facility:</b>	Northern Neck Electric Cooperative	<b>Date Sent to Facility</b>	6/21/96	
<b>Other Name:</b>		<b>Date Received by Facility</b>	6/24/96	
<b>EPA Assigned ID #:</b>	28700	<b>Date Response Received by EPA</b>	7/23/96	
		<b>Date of Letter</b>	7/19/96	
<b>Contact:</b>	Charles Rice			
<b>Address:</b>	PO Box 288 Warsaw VA 22572			
<b>Phone:</b>	804-333-3621			
<b>104(e) Response Comments:</b> 8/4/95 letter returned "no such PO Box # "				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Northern Printers Incorporated	<b>Date Sent to Facility</b>	6/21/96	
<b>Other Name:</b>		<b>Date Received by Facility</b>	6/24/96	
<b>EPA Assigned ID #:</b>	28725	<b>Date Response Received by EPA</b>		
		<b>Date of Letter</b>		
<b>Contact:</b>	The Ink Company			
<b>Address:</b>	8360 10 Ave. North Golden Valley MN 55426			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> 8/4/95 letter returned "no such street number." No response received. Equipment information taken from PCB facility file.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Northern REO Arribia Electric Corporation	<b>Date Sent to Facility</b>	8/ 4/95	5/21/96
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95	5/24/96
<b>EPA Assigned ID #:</b>	28750	<b>Date Response Received by EPA</b>		
		<b>Date of Letter</b>		
<b>Contact:</b>				
<b>Address:</b>	Box 217 Chama NM 87520			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> No response received. Information taken from PCB facility file.				
<b>Warning Letter Comments:</b>				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION****104(e) LETTER INFO****WARNING LETTER INFO****Facility:** Northland County Sub-United Properties**Other Name:****EPA Assigned ID #:** 28825**Date Sent to Facility**

8/ 4/95

**Date Received by Facility****Date Response Received by EPA****Date of Letter****Contact:****Address:** 408 St. Peter  
St. Paul MN 56102**Phone:****104(e) Response Comments:** 8/4/95 letter returned "attempted not known." Information taken from PCB facility file.**Warning Letter Comments:****Facility:** Northwestern Electric Cooperative, Incorpo**Other Name:****EPA Assigned ID #:** 28975**Date Sent to Facility**

8/ 4/95

**Date Received by Facility**

8/ 7/95

**Date Response Received by EPA**

9/ 5/95

**Date of Letter**

8/28/95

**Contact:** Chris Christopher / Franki**Address:** P.O. Box 2707  
Woodward OK 73802**Phone:** 405-256-7425**104(e) Response Comments:** Unable to locate PCB facility file. Oil in GE capacitors was Aroclor 1254.**Warning Letter Comments:****Facility:** Norwest Properties, Incorporated**Other Name:****EPA Assigned ID #:** 29025**Date Sent to Facility**

8/ 4/95

**Date Received by Facility**

8/ 8/95

**Date Response Received by EPA**

1/22/96

**Date of Letter**

1/15/96

**Contact:** Henry Marier**Address:** 255 Second Avenue South  
Minneapolis MN 55479**Phone:** 612-667-7289**104(e) Response Comments:** Company sold to Towle Real Estate prior to transport of equipment to PCB. Contact Dawn Grant, Towe Real Estate, 55 E. 5th St., St. Paul, MN 55101. Info taken from PCB facility file.**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** O'Brien & Gere Technical Services  
**Other Name:** (OBG Technical Services)  
**EPA Assigned ID #:** 29150

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) LETTER INFO**

8/ 4/95  
8/ 7/95

**WARNING LETTER INFO**

**Contact:** Linda O'Brien  
**Address:** PO Box 5240  
Syracuse NY 13220  
**Phone:** 315-437-6400

**104(e) Response Comments:** Response to 6/21/96 FU letter directs all correspondence to Beth MacManus, Westinghouse Electric Corp, 11 Stanwick St., #2167, Pittsburg, PA 15222

**Warning Letter Comments:**

**Facility:** O'Brien Machinery Co., The  
**Other Name:**  
**EPA Assigned ID #:** 34900

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95

**Contact:**  
**Address:** Green Street and Washingto  
Downingtown PA 19335  
**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned FOE. Equipment information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** O.H. Materials  
**Other Name:**  
**EPA Assigned ID #:** 29675

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

6/21/96

**Contact:** OHM Remediation  
**Address:** 18905 Irving St.  
Livonia MI 48152-3044  
**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned FOE. 6/21/96 letter sent to Livonia, MI. No response received, no signed green card. Equipment information taken from PCB facility file.

**Warning Letter Comments:**

Prepared by Dynamac Corporation  
Comment.DBF/J 1/21/97

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	Ohio Edison Company	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	29225	<b>Date Response Received by EPA</b>	9/ 8/95	
		<b>Date of Letter</b>	9/ 5/95	
<b>Contact:</b>	H.C. Couch			
<b>Address:</b>	76 South Main Street			
	Akron OH 44308			
<b>Phone:</b>	216-384-5151			
<b>104(e) Response Comments:</b> Ohio Edison claims no knowledge of shipment. According to fac files, one shipment of 350 capacitors was made.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Opelika Light & Power Department	<b>Date Sent to Facility</b>	8/ 4/95	5/21/96
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95	5/23/96
<b>EPA Assigned ID #:</b>	29375	<b>Date Response Received by EPA</b>		6/ 6/96
		<b>Date of Letter</b>		5/30/96
<b>Contact:</b>	Phillip Smitherman			
<b>Address:</b>	1010 Avenue C Box 390			
	Opelika AL 36801			
<b>Phone:</b>	334-705-5570			
<b>104(e) Response Comments:</b>				
<b>Warning Letter Comments:</b> Generator returned copy of original response dated 8/16/95. Original was not received by EPA.				
<b>Facility:</b>	Ordean Junior High School	<b>Date Sent to Facility</b>	8/ 4/95	5/21/96
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	5/23/96
<b>EPA Assigned ID #:</b>	29475	<b>Date Response Received by EPA</b>		6/12/96
		<b>Date of Letter</b>		6/ 3/96
<b>Contact:</b>	Kerry Leider			
<b>Address:</b>	215 NW First Ave East			
	Duluth MN 55802			
<b>Phone:</b>	218-723-4139			
<b>104(e) Response Comments:</b>				
<b>Warning Letter Comments:</b> Combined response with Lincoln Elementry School (25125). Warning letter sent in error.				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** Oscar Roberts Company

**Other Name:**

**EPA Assigned ID #:** 29550

**Contact:**

**Address:** 7250 France Avenue  
Edina MN 55435

**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned FOE. 6/21/96 letter sent to Brooklyn Park, NY returned FOE. Information taken from PCB facility file.

**Warning Letter Comments:**

---

**Facility:** Otis Elevator Company

**Other Name:**

**EPA Assigned ID #:** 29575

**Contact:** Joseph A. Santos

**Address:** 10 Farm Springs Road  
Farmington CT 06032

**Phone:**

**104(e) Response Comments:** Another manifest RCRA is NYA2500119.

**Warning Letter Comments:**

---

**Facility:** Otter Tail Power Company

**Other Name:**

**EPA Assigned ID #:** 29600

**Contact:** Mr. Terry Graumann

**Address:** PO Box 496  
Fergus Falls MN 56538-0496

**Phone:** 218-739-8200

**104(e) Response Comments:** See 104(e) response file for general comments made by RPM. Additional RCRA ID is NDD00819201 (facility in Wahpeton, ND)

**Warning Letter Comments:**

---

**104(e) LETTER INFO****WARNING LETTER INFO**

---

**Date Sent to Facility**

6/21/96

**Date Received by Facility**

**Date Response Received by EPA**

**Date of Letter**

**Date Sent to Facility**

8/ 4/95

**Date Received by Facility**

8/ 7/95

**Date Response Received by EPA**

10/19/95

**Date of Letter**

10/17/95

**Date Sent to Facility**

8/ 4/95

**Date Received by Facility**

8/ 7/95

**Date Response Received by EPA**

9/ 8/95

**Date of Letter**

9/ 5/95

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Owens Corning Fiberglass Corporation	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	9/22/95
EPA Assigned ID #:	29625	Date Response Received by EPA	9/22/95
		Date of Letter	9/20/95
Contact:	Joyce A. Graves		
Address:	Fiberglas Tower		
	Toledo OH 43659		
Phone:	419-248-8000		
104(e) Response Comments:	Conflict of information between 104(e) and fac file. Information taken from facility file.		
Warning Letter Comments:			
Facility:	Owens Illinois Plant 94	Date Sent to Facility	8/ 4/95
Other Name:	(Owens-Illinois, Inc.)	Date Received by Facility	8/ 7/95
EPA Assigned ID #:	29650	Date Response Received by EPA	9/ 1/95
		Date of Letter	8/31/95
Contact:	Robert Towles		
Address:	One SeaGate - 30 LDP		
	Toledo OH 43666		
Phone:	419-247-7895		
104(e) Response Comments:	Information regarding shipments made to PCB is included in the High Voltage Maintenance response.		
Warning Letter Comments:			
Facility:	PCB Disposal Systems, Inc.	Date Sent to Facility	6/21/96
Other Name:		Date Received by Facility	6/24/96
EPA Assigned ID #:	29950	Date Response Received by EPA	8/23/96
		Date of Letter	8/ 8/96
Contact:	Edward R. Sechrist		
Address:	1483 SW 58 Highway		
	Kingsville MO 64061		
Phone:	816-732-5561		
104(e) Response Comments:	Response received from Essex Waste Management states that PCB Disposal Systems, Inc. changed it's name to AmerEco in 1987 and dissolved in 1992 after bankruptcy proceedings. Essex currently owns the property and has no knowledge or information regarding		
Warning Letter Comments:	shipments made to PCB. Equipment information taken from PCB facility file. Includes information for both KC and Kingsville facility.		

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	PKM Electric Cooperative, Incorporated	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	30225	Date Response Received by EPA	10/ 4/95
		Date of Letter	10/ 2/95
Contact:	Bob Kliner		
Address:	Box 108		
	Warren MN 56762		
Phone:			
104(e) Response Comments:	Generator has no knowledge or information regarding equipment sent to PCB. Information taken from PCB facility file.		
Warning Letter Comments:			
Facility:	PSI Piping Specialties	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	30625	Date Response Received by EPA	
		Date of Letter	
Contact:	F.L. Roudebush		
Address:	Box 15512		
	Kansas City MO 64106		
Phone:			
104(e) Response Comments:	8/4/95 letter returned "unclaimed." Equipment information taken from PCB facility file. The capacitor log for HWM #1131 is marked "not complete."		
Warning Letter Comments:			
Facility:	PacifiCorp Pacific Power Utah Power	Date Sent to Facility	8/ 4/95
Other Name:	(Pacific Power & Light Company)	Date Received by Facility	8/ 6/95
EPA Assigned ID #:	29725	Date Response Received by EPA	10/10/95
		Date of Letter	10/ 6/95
Contact:	Charles P. Allen		
Address:	920 SW 6th Avenue		
	Portland OR 97204		
Phone:	503-464-6477		
104(e) Response Comments:	Generator has no knowledge or information regarding equipment sent to PCB. Information taken from PCB facility file.		
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** Pacific County PUD  
**Other Name:**  
**EPA Assigned ID #:** 29700

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 9/28/95  
**Date of Letter**

**104(e) LETTER INFO****WARNING LETTER INFO**

---

**Contact:** Doug Miller  
**Address:** Box 472  
Raymond WA 98577  
**Phone:**

**104(e) Response Comments:** 104(e) response states that 3 transformers were sent to PCB. Facility files only show that 2 were received.  
**Warning Letter Comments:**

---

**Facility:** Paint & Assembly Corporation  
**Other Name:**  
**EPA Assigned ID #:** 29775

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 8/95  
**Date Response Received by EPA** 9/11/95  
**Date of Letter** 9/ 6/95

**Contact:** Christopher A. Courtney  
**Address:** PO Box 496  
Elwood IN 46036  
**Phone:** 317-552-4030

**104(e) Response Comments:** Future correspondence is also to be sent to Thomas L. Russell at Paint & Assembly Corp.  
**Warning Letter Comments:**

---

**Facility:** Papago Power Incorporated  
**Other Name:**  
**EPA Assigned ID #:** 29825

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA**  
**Date of Letter**

6/21/96

**Contact:** Walter C. Austin  
**Address:** 945 W. Silverlake  
Tucson AZ 85713  
**Phone:**

**104(e) Response Comments:**  
**Warning Letter Comments:** Warning letter returned - refused. Information taken from PCB facility file.

---



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Paramount Group Incorporated	Date Sent to Facility	6/21/96
Other Name:		Date Received by Facility	6/24/96
EPA Assigned ID #:	29850	Date Response Received by EPA	
		Date of Letter	
Contact:	Gregg Izzo		
Address:	1633 Broadway, #1801		
	New York NY 10019		
Phone:	212-237-3100		
104(e) Response Comments: FOIA request received 7/2/96. FOIA sent 8/5/96. No response received. Information taken from PCB facility file.			
Warning Letter Comments:			
Facility:	Paulding Putnan Electric Cooperative, Inc.	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	29900	Date Response Received by EPA	9/ 5/95
		Date of Letter	8/30/95
Contact:	William Carnahan		
Address:	11957 US Hwy 127		
	Paulding OH 45879		
Phone:	419-399-5015		
104(e) Response Comments: All data between 104(e) response and PCB facility file is conflicting. Appears that their may have been a second shipment			
Warning Letter Comments:			
Facility:	Pawhuska Light Department, City of	Date Sent to Facility	8/ 4/95 5/21/96
Other Name:		Date Received by Facility	8/ 8/95 5/23/96
EPA Assigned ID #:	15325	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	700 West 10th Box 5		
	Pawhuska OK 74056		
Phone:			
104(e) Response Comments:			
Warning Letter Comments: No response received. Information taken from PCB facility file.			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	Penn Yan Municipal Utilities	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95	
<b>EPA Assigned ID #:</b>	30025	<b>Date Response Received by EPA</b>	10/ 6/95	
		<b>Date of Letter</b>	10/ 3/95	
<b>Contact:</b>	John W. Dreste, Esq.			
<b>Address:</b>	2 Maiden Lane			
	Penn Yan NY 14527			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> Generator has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Penske Truck Leasing Co.	<b>Date Sent to Facility</b>	6/21/96	
<b>Other Name:</b>	(Pensky Tank Company)	<b>Date Received by Facility</b>	6/24/96	
<b>EPA Assigned ID #:</b>	30050	<b>Date Response Received by EPA</b>	8/16/96	
		<b>Date of Letter</b>	8/13/96	
<b>Contact:</b>	Marc Althen			
<b>Address:</b>	PO Box 563			
	Reading PA 19603-0563			
<b>Phone:</b>	610-775-6268			
<b>104(e) Response Comments:</b> 8/4/95 letter returned "no such number." The weight of 1198# was based on the 440 Qt on the disposal manifest and the formula 10.89#/gal.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Pepper Industries	<b>Date Sent to Facility</b>	6/21/96	
<b>Other Name:</b>		<b>Date Received by Facility</b>	6/24/96	
<b>EPA Assigned ID #:</b>	30075	<b>Date Response Received by EPA</b>		
		<b>Date of Letter</b>		
<b>Contact:</b>	John Jones			
<b>Address:</b>	2735 Villa Creek Drive, Suti			
	Dallas TX 75234			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> 8/4/95 letter returned "no such number." No response received.				
<b>Warning Letter Comments:</b>				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	Pierre, City of	Date Sent to Facility	8/ 4/95	5/21/96
Other Name:	(Pierre Municipal Power & Light)	Date Received by Facility	8/ 7/95	5/24/96
EPA Assigned ID #:	30150	Date Response Received by EPA		6/10/96
		Date of Letter		6/ 5/96
Contact:	Todd Chambers			
Address:	222 E. Dakota Avenu Pierre SD 57501			
Phone:	605-773-7341			
104(e) Response Comments:				
Warning Letter Comments:	Generator submitted 3 copies of HWM #0001 with different TSDF signature dates.			
Facility:	Pinnacle	Date Sent to Facility	8/ 4/95	
Other Name:	(New Market Holding Company)	Date Received by Facility	8/10/95	
EPA Assigned ID #:	27925	Date Response Received by EPA		
		Date of Letter		
Contact:	David Malo			
Address:	PO Box 407 Marlboro NY 07746-0407			
Phone:	908-972-5600			
104(e) Response Comments:	8/30/95 letter received from generator acknowledging extion to 9/30/95. No response received. Equipment information taken from PCB facility file.			
Warning Letter Comments:				
Facility:	Pioneer REC, Incorporated	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	30175	Date Response Received by EPA	8/21/95	
		Date of Letter	8/18/95	
Contact:	Douglas Haas			
Address:	344 West U.S. Route 36, P.O. Piqua OH 45356			
Phone:	513-773-2523			
104(e) Response Comments:	Certificate of Destruction was issued prior to disposal manifest disposal date.			
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Piqua, City of  
**Other Name:** (Piqua Municipal Power Systems)  
**EPA Assigned ID #:** 30200

**Contact:** Sam Shaw / Richard Mille  
**Address:** 123 Bridge Street  
Piqua OH 45356  
**Phone:** 513-778-2077

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 9/14/95  
**Date of Letter** 9/11/95

**104(e) LETTER INFO**

**WARNING LETTER INFO**

**104(e) Response Comments:** Other generator contact Richard Miller, address and phone are the same.  
**Warning Letter Comments:**

**Facility:** Polk-Burnett Electric Cooperative  
**Other Name:**  
**EPA Assigned ID #:** 30375

**Contact:** Joseph A. Sobol  
**Address:** 1000 Highway #35  
Centuria WI 54824  
**Phone:** 715-646-2191

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 9/ 8/95  
**Date of Letter** 9/ 6/95

**104(e) Response Comments:** Generator claims that their files were maintained by Dairyland Coop. There is no information in the Dairyland Coop facility file or 104(e) response regarding this facility. There are no PCB facility files for this facility.  
**Warning Letter Comments:**

**Facility:** Poly Institute of New York  
**Other Name:**  
**EPA Assigned ID #:** 30400

**Contact:**  
**Address:** Route 110  
Farmingdale NY 11735  
**Phone:**

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 8/95  
**Date Response Received by EPA**  
**Date of Letter**

5/21/96  
5/24/96

**104(e) Response Comments:**  
**Warning Letter Comments:** ~~No response received.~~ Equipment information taken from PCB facility file.

*Resp received 10/30/96,  
dated 10/28/96*

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** Pottsville Hospital and Warne Clinic  
**Other Name:** (Pottsville Hospital)  
**EPA Assigned ID #:** 30425

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 10/ 2/95  
**Date of Letter** 9/26/95

---

**104(e) LETTER INFO**

---

**WARNING LETTER INFO**

**Contact:** John E. Simodejka  
**Address:** 420 South Jackson Street  
Pottsville PA 17901  
**Phone:** 717-621-5111

**104(e) Response Comments:** Generator provided no information regarding HWM #2741-6. Information taken from PCB facility file.

**Warning Letter Comments:**

---

**Facility:** Price Electric  
**Other Name:**  
**EPA Assigned ID #:** 30525

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA**  
**Date of Letter**

5/21/96  
5/24/96  
6/28/96  
6/21/96

**Contact:** Le Roy Hanson  
**Address:** 508 North Lake Ave  
Philips WI 54555  
**Phone:** 715-339-2155

**104(e) Response Comments:**

**Warning Letter Comments:** Generator believed that Dairyland Power had responded in their behalf.

---

**Facility:** Prime Group, Inc.  
**Other Name:** (Blawnox Foundry & Mill Machine)  
**EPA Assigned ID #:** 12275

**Date Sent to Facility** 6/21/96  
**Date Received by Facility** 6/24/96  
**Date Response Received by EPA** 7/26/96  
**Date of Letter**

**Contact:** Donald Anderson  
**Address:** 4527 Columbia Ave.  
Hammond IN 46327  
**Phone:** Unk

**104(e) Response Comments:** 8/4/95 letter returned "FOE." Respondent has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.

**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	Public Utility District #1 of Okanogan Coun	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>	(Public Utility District #1)	<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	29325	<b>Date Response Received by EPA</b>	9/ 8/95	
		<b>Date of Letter</b>	9/ 5/95	
<b>Contact:</b>	Donald B. Brantner			
<b>Address:</b>	Box 912			
	Okangan WA 98840			
<b>Phone:</b>	509-422-8421			
<b>104(e) Response Comments:</b> Conflicting info between 104(e) & fac file. Info taken from 104(e).				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Quandel Group Inc.	<b>Date Sent to Facility</b>	8/ 4/95	5/21/96
<b>Other Name:</b>	(Noble-Quandel)	<b>Date Received by Facility</b>	8/ 7/95	5/24/96
<b>EPA Assigned ID #:</b>	28200	<b>Date Response Received by EPA</b>		6/24/96
		<b>Date of Letter</b>		6/20/96
<b>Contact:</b>	Noble C. Quandel			
<b>Address:</b>	PO Box 6072			
	Harrisburg PA 17112-0072			
<b>Phone:</b>	717-657-0909			
<b>104(e) Response Comments:</b> 8/4/95 letter burned in a fire.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Quatronix Corporation/Excel	<b>Date Sent to Facility</b>	6/21/96	
<b>Other Name:</b>		<b>Date Received by Facility</b>	6/24/96	
<b>EPA Assigned ID #:</b>	30925	<b>Date Response Received by EPA</b>		
		<b>Date of Letter</b>		
<b>Contact:</b>				
<b>Address:</b>	45 Adams Avenue			
	Hauppauge NY 11788			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> 8/4/95 letter returned FOE. No response. Equipment information taken from PCB facility file.				
<b>Warning Letter Comments:</b>				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** R.T. French Company  
**Other Name:**  
**EPA Assigned ID #:** 31850

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) LETTER INFO**

6/21/96

**WARNING LETTER INFO**

**Contact:**  
**Address:** Souderton Pike  
Souderton PA 18694  
**Phone:**

**104(e) Response Comments:** Letters have been sent to Souderton Pike, 53 Hatfield Road, and 11461 Lebanon Road. All mail has been returned FOE. Equipment information taken from PCB facility file.

**Warning Letter Comments:**

---

**Facility:** Raytheon Company  
**Other Name:**  
**EPA Assigned ID #:** 31025

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/10/95  
**Date Response Received by EPA** 10/ 2/95  
**Date of Letter** 9/25/95

**Contact:** Jeffrey B. Axelrod  
**Address:** 141 Spring Street  
Lexington MA 02173  
**Phone:** 617-860-2803

**104(e) Response Comments:** Generator has no knowledge or documents pertaining to shipments sent to PCB. Info taken from PCB facility file.

**Warning Letter Comments:**

---

**Facility:** Recovery Specialists Incorporated  
**Other Name:**  
**EPA Assigned ID #:** 31200

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA**  
**Date of Letter**

**Contact:** Fred Feitel  
**Address:** PO Box 255  
Saline MI 48176  
**Phone:** 313-990-0986

**104(e) Response Comments:** Letter received 10/17/95 requesting extension until 10/30/95. No response. Equipment information taken from PCB facility file.

**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	Remcor	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/21/95	
EPA Assigned ID #:	31250	Date Response Received by EPA	9/22/95	
		Date of Letter	9/15/95	
Contact:	Tony Monforte			
Address:	Blackhorse Pike Williamstown NJ 08094			
Phone:				
104(e) Response Comments: Correspondence from Jr. Caparrelli stated that Mr. Monforte is deceased and the company is out of business. Information taken from PCB facility file.				
Warning Letter Comments:				
Facility:	Republic Steel Corporation Bar Division	Date Sent to Facility	8/ 4/95	5/21/96
Other Name:		Date Received by Facility	8/ 7/95	5/23/96
EPA Assigned ID #:	31300	Date Response Received by EPA		
		Date of Letter		
Contact:	Ted Zalenski			
Address:	25 W. Prospect Ave Cleveland OH 44115-1069			
Phone:	216-622-5000			
104(e) Response Comments: FOIA request received 9/5/96. FOIA sent 9/25/95.				
Warning Letter Comments:				
Facility:	Richland, City of	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	15400	Date Response Received by EPA		
		Date of Letter		
Contact:	M. Estes			
Address:	505 Swift Blvd. Box Richland WA 99352			
Phone:				
104(e) Response Comments: No response received. Equipment information taken from PCB facility file.				
Warning Letter Comments:				



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Roberts Foundry	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	31425	Date Response Received by EPA	
		Date of Letter	
Contact:	F.A. Kulju Grede F		
Address:	Box 3228		
	Greenwood SC 29648		
Phone:			
104(e) Response Comments:	8/4/95 letter returned FOE.		
Warning Letter Comments:			
Facility:	Rock River Water Reclamation District	Date Sent to Facility	6/21/96
Other Name:	(Sanitary District of Rockford)	Date Received by Facility	6/24/96
EPA Assigned ID #:	32000	Date Response Received by EPA	7/16/96
		Date of Letter	7/11/96
Contact:	John Roseberg		
Address:	PO Box 7480		
	Rockford IL 61126-7480		
Phone:	815-397-9700		
104(e) Response Comments:	8/4/95 letter returned - attempted not known.		
Warning Letter Comments:			
Facility:	Rockwell International	Date Sent to Facility	6/21/96
Other Name:		Date Received by Facility	6/24/96
EPA Assigned ID #:	31500	Date Response Received by EPA	7/25/96
		Date of Letter	7/19/96
Contact:	Robert Beck		
Address:	625 Liberty		
	Pittsburg PA 15222-3123		
Phone:	412-565-5818		
104(e) Response Comments:	8/4/95 letter returned FOE. Followup 104(e) sent to Frankfurt KY address. This generator has no knowledge or information regarding shipment sent to PCB. Information taken from PCB facility file.		
Warning Letter Comments:			

***PCB Treatment, Inc. General Information***  
***Review of Facilities Requiring Follow-up and Warning Letters***

**GENERAL INFORMATION**

**Facility:** Roger W. Soderstrom  
**Other Name:**  
**EPA Assigned ID #:** 31525

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) LETTER INFO**

6/21/96  
6/24/96

**WARNING LETTER INFO**

**Contact:**  
**Address:** 13929 Saint Francis Blvd.  
Ramsey MN 55303  
**Phone:**

**104(e) Response Comments:** No response. Equipment information taken from PCB facility file.  
**Warning Letter Comments:**

**Facility:** Ross Service Company, Incorporated  
**Other Name:**  
**EPA Assigned ID #:** 31700

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 8/28/95  
**Date of Letter** 8/21/95

**Contact:** John Ross  
**Address:** Box 215  
Coleman SD 57017  
**Phone:** 605-534-3651

**104(e) Response Comments:** Generator has no knowledge or information regarding shipments made to PCB. Information take from PCB facility file.  
**Warning Letter Comments:**

**Facility:** Rural Electric Commission  
**Other Name:**  
**EPA Assigned ID #:** 31750

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**Contact:**  
**Address:** Potter NE 69156  
**Phone:**

**104(e) Response Comments:** Combined response with Rural Electric Company (31775).  
**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** Rural Electric Company  
**Other Name:**  
**EPA Assigned ID #:** 31775

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

---

**104(e) LETTER INFO**

8/ 4/95  
8/ 8/95  
9/ 7/95  
9/ 5/95

---

**WARNING LETTER INFO**

**Contact:** Lloyd Sisson  
**Address:** Box 518  
Pine Bluffs WY 82082  
**Phone:** 307-245-3261

**104(e) Response Comments:** Combined response with Rural Electric Commission (Potter, NE).  
**Warning Letter Comments:**

---

**Facility:** Russ Cargill Company  
**Other Name:**  
**EPA Assigned ID #:** 31675

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**Contact:** LeRaye M. Osborne  
**Address:** PO Box 5624  
Minneapolis MN 55440-5624  
**Phone:**

**104(e) Response Comments:** Combined response with Cargill (31625)  
**Warning Letter Comments:**

---

**Facility:** S.E. Iowa Cooperative Electric  
**Other Name:**  
**EPA Assigned ID #:** 34625

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 8/95  
**Date Response Received by EPA** 9/ 8/95  
**Date of Letter** 9/ 6/95

**Contact:** Robert Swindell  
**Address:** P.O. Box 440  
Mt. Pleasant IA 52641  
**Phone:** 319-385-1577

**104(e) Response Comments:** Generator has no knowledge or documents pertaining to shipments made to PCB. Info taken from PCB facility files.  
**Warning Letter Comments:**

---

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	SEPTA	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 8/95
EPA Assigned ID #:	32200	Date Response Received by EPA	10/ 6/95
		Date of Letter	10/ 5/95
Contact:	Eugene N. Cipriani		
Address:	1234 Market Street - 5th Flo		
	Philadelphia PA 19107-3780		
Phone:			
104(e) Response Comments:	Unable to locate PCB facility file for this generator. Information taken from 104(e) only.		
Warning Letter Comments:			
Facility:	SGL Carbon	Date Sent to Facility	8/ 4/95
Other Name:	(Great Lakes Carbon Corp.)	Date Received by Facility	8/ 9/95
EPA Assigned ID #:	21550	Date Response Received by EPA	9/ 8/95
		Date of Letter	9/ 7/95
Contact:	Douglas R. Gunson		
Address:	8600 Bill Ficklen Drive		
	Charlotte NC 28269		
Phone:	704-593-5170		
104(e) Response Comments:	Unable to locate PCB facility file for this generator. Information taken from 104(e) only.		
Warning Letter Comments:			
Facility:	SHC Incorporated	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	32325	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	296 Broadway		
	Passaic NJ 07055		
Phone:			
104(e) Response Comments:	No returned mail, no returned signed green card, no response. Unable to locate PCB facility file. Equipment information taken from "Session" file.		
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	SKF Foundry Division	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	32725	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	1004 West Main Stre Washington MO 63090-100		
Phone:			
104(e) Response Comments:	8/4/95 letter returned FOE. Equipment information taken from PCB facility file.		
Warning Letter Comments:			
Facility:	Sallisaw, City of	Date Sent to Facility	6/24/96
Other Name:	(Sallisaw Municipal Light & Power)	Date Received by Facility	6/24/96
EPA Assigned ID #:	31925	Date Response Received by EPA	8/19/96
		Date of Letter	8/16/96
Contact:	James R. Hudgens		
Address:	PO Box 525 Sallisaw OK 74955		
Phone:	Unk		
104(e) Response Comments:	8/4/95 letter returned attempted - not known.		
Warning Letter Comments:			
Facility:	Sandoz Incorporated	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 8/95
EPA Assigned ID #:	31975	Date Response Received by EPA	
		Date of Letter	
Contact:	Mr. J. Smith		
Address:	59 Route 10 Buildin East Hanove NJ 07936		
Phone:			
104(e) Response Comments:	Letter received 8/30/95 from Mr. Paul Neale confirming 30-day extension. No response received. Unable to locate PCB facility file. Equipment information taken from PCB facility file.		
Warning Letter Comments:			

*Resp received 9/30/96, dated 9/27/96*

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Santee Cooper  
**Other Name:**  
**EPA Assigned ID #:** 32025

**Contact:** Phil Pierce  
**Address:** 1 Riverwood Drive, P.O. Box  
Moncks Corner SC 29461-2901  
**Phone:** 803-761-8000

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 10/ 5/95  
**Date of Letter** 10/ 3/95

**104(e) LETTER INFO**

**WARNING LETTER INFO**

**104(e) Response Comments:** Information regarding the quantity of equipment conflicts within the 104(e) response.  
**Warning Letter Comments:**

**Facility:** Sanyo Corporation  
**Other Name:**  
**EPA Assigned ID #:** 32050

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA**  
**Date of Letter**

**Contact:**  
**Address:** 1751 Sheridan Stree  
Richmond IN 47374  
**Phone:**

**104(e) Response Comments:** No response. Equipment information taken from PCB facility file.  
**Warning Letter Comments:**

**Facility:** Schuylkill Haven, Borough of  
**Other Name:**  
**EPA Assigned ID #:** 12650

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA**  
**Date of Letter**

**Contact:**  
**Address:** 39 Dock Street  
Schuylkill PA 17972  
**Phone:**

**104(e) Response Comments:** No response received. Information taken from PCB facility file.  
**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	Shakstad Electric	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/10/95	
EPA Assigned ID #:	32300	Date Response Received by EPA	8/28/95	
		Date of Letter	8/24/95	
Contact:	Lloyd C. Richardson, Jr.			
Address:	1400 Industrial Ave			
	Sioux Falls SD 57101			
Phone:	605-225-6310			
104(e) Response Comments: Generator has no knowledge or documents pertaining to shipments made to PCB. Information was taken from PCB facility file.				
Warning Letter Comments:				
Facility:	Shenandoah Valley Electric Cooperative	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	32400	Date Response Received by EPA	9/ 1/95	
		Date of Letter	8/28/95	
Contact:	James S. Huggard			
Address:	P.O. Box 236			
	Mt. Crawford VA 22841			
Phone:	540-434-2200			
104(e) Response Comments: Unable to locate PCB facility file for HWM #1100.				
Warning Letter Comments:				
Facility:	Shenango, Inc.	Date Sent to Facility	6/21/96	
Other Name:		Date Received by Facility	6/24/96	
EPA Assigned ID #:	32425	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	200 Neville Road			
	Pittsburg PA 15225			
Phone:				
104(e) Response Comments: 8/4/95 letter returned FOE. No response received. Equipment information taken from PCB facility file.				
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Sherrill, City of	Date Sent to Facility	8/ 4/95
Other Name:	(Sherrill Power & Light)	Date Received by Facility	8/ 7/95
EPA Assigned ID #:	32500	Date Response Received by EPA	9/ 5/95
		Date of Letter	8/28/95
Contact:	Keith D. Pitman		
Address:	601 Sherrill Road		
	Sherrill NY 13461		
Phone:	315-363-2440		
104(e) Response Comments: Unable to locate PCB facility file. HWM # is unknown.			
Warning Letter Comments:			
Facility:	Shrake Electric Corporation	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 5/95
EPA Assigned ID #:	32550	Date Response Received by EPA	8/25/95
		Date of Letter	8/21/95
Contact:	Elizabeth Lee Rohleder		
Address:	618 S. Kansas Avenue, Ste.		
	Topeka KS 66603-3804		
Phone:	913-233-9262		
104(e) Response Comments: Generator has no knowledge or documents pertaining to shipments made to PCB. Information was taken from PCB facility file.			
Warning Letter Comments:			
Facility:	Sibley Machine & Foundry Corporation	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	32600	Date Response Received by EPA	9/25/95
		Date of Letter	9/20/95
Contact:	Donald L. Martin		
Address:	206 E. Tutt St., Box 40		
	South Bend IN 46623		
Phone:	219-288-4611		
104(e) Response Comments: Generator has no knowledge or documents pertaining to shipments made to PCB. Information was taken from PCB facility file.			
Warning Letter Comments:			



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Silas Bolef Company	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	32675	Date Response Received by EPA	8/21/95
		Date of Letter	8/18/95
Contact:	William Lessing		
Address:	Forest Avenue & Lafayette St Norristown PA 19401		
Phone:	610-272-3223		
104(e) Response Comments: Generator has no knowledge or information regarding shipments sent to PCB. Information taken from PCB facility file.			
Warning Letter Comments:			
Facility:	Sola Electric (Hevi-Duty)	Date Sent to Facility	8/ 4/95
Other Name:	(Dowzer Electric)	Date Received by Facility	8/ 7/95
EPA Assigned ID #:	17975	Date Response Received by EPA	9/ 8/95
		Date of Letter	9/ 5/95
Contact:	John J. Dougherty		
Address:	2701 US Hwy 1175 Goldsboro NC 27530		
Phone:	919-734-8900		
104(e) Response Comments: Generator requested correspondence be sent to John J. Dougherty, Director of Environmental & Safety Compliance, PO Box 268, Goldsboro, NC 27530.			
Warning Letter Comments:			
Facility:	Solomon Corporation	Date Sent to Facility	8/ 4/95
Other Name:	(Solomon Electric)	Date Received by Facility	8/ 7/95
EPA Assigned ID #:	32775	Date Response Received by EPA	9/ 5/95
		Date of Letter	9/ 1/95
Contact:	Dana Gilfillan		
Address:	Box 245 Solomon KS 67480		
Phone:	913-655-2191		
104(e) Response Comments: Unable to locate PCB facility file. Information taken from 104(e) only.			
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Solvay, Village of	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	36900	Date Response Received by EPA	
		Date of Letter	
Contact:	Barbara A. Harrington		
Address:	507 Charles Ave		
	Solvay NY 13209		
Phone:	315-468-6229		
104(e) Response Comments: Letter received 9/6/95 confirms extension to 9/25/95. No response received. Unable to locate PCB facility file. Equipment information taken from "Session" file.			
Warning Letter Comments:			
Facility:	South Central Power	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	32900	Date Response Received by EPA	10/ 6/95
		Date of Letter	10/ 5/95
Contact:	Philip W. Lee, Esq.		
Address:	10 West Broad Street		
	Columbus OH 43215-3435		
Phone:	614-469-3200		
104(e) Response Comments: Unable to locate facility files for HWM #3083 and #1279. Information taken from 104(e) response.			
Warning Letter Comments:			
Facility:	South St. Paul Public Schools	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	32975	Date Response Received by EPA	9/18/95
		Date of Letter	9/14/95
Contact:	Glen Birnstengel		
Address:	700 Second Street North		
	South St. Paul MN 55075		
Phone:	612-457-9465		
104(e) Response Comments: Unable to locate PCB facility file. Information taken from 104(e) only.			
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

<b>GENERAL INFORMATION</b>		<b>104(e) LETTER INFO</b>	<b>WARNING LETTER INFO</b>
<b>Facility:</b>	Southdale Medical Building	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/10/95
<b>EPA Assigned ID #:</b>	33000	<b>Date Response Received by EPA</b>	9/21/95
		<b>Date of Letter</b>	9/20/95
<b>Contact:</b>	Michael H. Maney		
<b>Address:</b>	6545 France Avenue South Minneapolis MN 55429		
<b>Phone:</b>	612-922-5399		
<b>104(e) Response Comments:</b> Southdale Medical Building is under new ownership. New owners have no knowledge or information regarding shipments made to PCB. Info taken from PCB facility file.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Southeastern Illinois Electric Cooperative I	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	33050	<b>Date Response Received by EPA</b>	9/ 5/95
		<b>Date of Letter</b>	8/29/95
<b>Contact:</b>	Michael W. Peters, Genera		
<b>Address:</b>	Box 251 Eldorado IL 62930		
<b>Phone:</b>	217-529-5561		
<b>104(e) Response Comments:</b> Unable to locate any PCB files for this facility. Information taken from 104 (e) response.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Southern Indiana Rural Electric Cooperativ	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 5/95
<b>EPA Assigned ID #:</b>	33175	<b>Date Response Received by EPA</b>	9/ 5/95
		<b>Date of Letter</b>	9/ 1/95
<b>Contact:</b>	Michael E. Hammack		
<b>Address:</b>	1776 10th St., Box 219 Tell City IN 47586		
<b>Phone:</b>	812-547-2316		
<b>104(e) Response Comments:</b> Unable to locate PCB facility file for HWM #0738B. Information taken from 104(e) response.			
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	Southern Power District	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>	(Southern Nebraska Rural Public Power)	<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	33200	<b>Date Response Received by EPA</b>	9/ 5/95	
		<b>Date of Letter</b>	9/ 1/95	
<b>Contact:</b>	Tim Stanton			
<b>Address:</b>	Box 1687, 1306 W. 3 Grand Island NE 68802			
<b>Phone:</b>	308-384-2350			
<b>104(e) Response Comments:</b> Response includes information for Franklin Rural Public Power District (20400).				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Southside Electric Cooperative	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	33225	<b>Date Response Received by EPA</b>	9/18/95	
		<b>Date of Letter</b>		
<b>Contact:</b>	James D. Oakes			
<b>Address:</b>	Box 7 Crewe VA 23930			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> Generator did not provide any information regarding HWM #2707.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Southwest Central Rural Electric Cooperati	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	33250	<b>Date Response Received by EPA</b>	9/ 7/95	
		<b>Date of Letter</b>	9/ 5/95	
<b>Contact:</b>	Michael N. Vaporis, Esq.			
<b>Address:</b>	917 Philadelphia St. Indiana PA 15701			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> Generator has no knowledge or documents pertaining to shipments made to PCB. Information was taken from PCB facility files.				
<b>Warning Letter Comments:</b>				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO	
Facility:	Southwest Recyclers	Date Sent to Facility	6/21/96		
Other Name:		Date Received by Facility	6/24/96		
EPA Assigned ID #:	33300	Date Response Received by EPA			
		Date of Letter			
Contact:					
Address:	Box 1595				
	Bloomfield				
	NM 87413				
Phone:					
104(e) Response Comments: 8/4/95 letter returned "insufficient address." No response received. Equipment information taken from PCB facility file.					
Warning Letter Comments:					
Facility:	Soyland Power Cooperative, Incorporated	Date Sent to Facility	8/ 4/95		
Other Name:	(Western Illinois Power Coop)	Date Received by Facility	8/ 7/95		
EPA Assigned ID #:	37575	Date Response Received by EPA	9/ 1/95		
		Date of Letter	8/29/95		
Contact:	Robert K. Harbour				
Address:	788 N. Sunnyside Road				
	Decatur				
	IL 62522				
Phone:	217-423-0021				
104(e) Response Comments: Unable to locate PCB facility file for HWM #0582. Information taken from 104(e) only.					
Warning Letter Comments:					
Facility:	Spangler Candy Company	Date Sent to Facility	8/ 4/95		
Other Name:		Date Received by Facility	8/ 8/95		
EPA Assigned ID #:	33325	Date Response Received by EPA	8/28/95		
		Date of Letter	8/17/95		
Contact:	Paul Gackel				
Address:	400 N. Portland, PO Box71				
	Bryan				
	OH 43506				
Phone:	419-636-4221				
104(e) Response Comments: HWM #1840 facility file indicates 17 caps were received. 104(e) response shows 1 cap. Generator was invoiced for 1 cap.					
Warning Letter Comments:					

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	Square D Company	<b>Date Sent to Facility</b>	6/21/96	
<b>Other Name:</b>		<b>Date Received by Facility</b>	6/24/96	
<b>EPA Assigned ID #:</b>	33500	<b>Date Response Received by EPA</b>	8/21/96	
		<b>Date of Letter</b>	8/15/96	
<b>Contact:</b>	Gladys M. Thomas			
<b>Address:</b>	1415 S. Roselle Rd. Palatine IL 60067			
<b>Phone:</b>	708-397-2600			
<b>104(e) Response Comments:</b>	8/4/95 letter returned FOE.			
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	St. Charles Electric Utilities	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>	(St. Charles, City of)	<b>Date Received by Facility</b>	8/ 8/95	
<b>EPA Assigned ID #:</b>	33850	<b>Date Response Received by EPA</b>	10/ 2/95	
		<b>Date of Letter</b>	9/28/95	
<b>Contact:</b>	Patrick J. Boyle			
<b>Address:</b>	2 East Main St. Charles IL 60174			
<b>Phone:</b>	708-377-4407			
<b>104(e) Response Comments:</b>	Combined response with St. Charles Electric Coop (33825). Unable to locate PCB facility files for HWM #0740, 1255, 1129, and 2174. Information taken from 104(e) response.			
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	St. Clair Die Casting Company	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	33875	<b>Date Response Received by EPA</b>	8/31/95	
		<b>Date of Letter</b>	8/29/95	
<b>Contact:</b>	Jim Wall			
<b>Address:</b>	P.O. Box 280, St. Clair Indus St. Clair MO 63077-0280			
<b>Phone:</b>	314-629-2550			
<b>104(e) Response Comments:</b>	Unable to locate PCB facility file for this generator. Information taken from 104(e) only.			
<b>Warning Letter Comments:</b>				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	St. Francis Medical Center & Home	<b>Date Sent to Facility</b>	6/21/96	
<b>Other Name:</b>	(Medical Arts Building)	<b>Date Received by Facility</b>	6/24/96	
<b>EPA Assigned ID #:</b>	26275	<b>Date Response Received by EPA</b>	8/ 2/96	
		<b>Date of Letter</b>	8/ 2/96	
<b>Contact:</b>	Gerald Bjerken			
<b>Address:</b>	415 Oak St. Breckenridge MN 56520			
<b>Phone:</b>	218-643-3000			
<b>104(e) Response Comments:</b> 8/4/95 letter returned "incomplete address." Respondent has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	St. Francis Municipal Water & Light	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	33950	<b>Date Response Received by EPA</b>		
		<b>Date of Letter</b>		
<b>Contact:</b>				
<b>Address:</b>	Box 861 St. Francis KS 67756			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> No response received. Equipment information taken from PCB facility file.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	St. Joseph Light & Power Company	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95	
<b>EPA Assigned ID #:</b>	34000	<b>Date Response Received by EPA</b>	9/ 7/95	
		<b>Date of Letter</b>	9/ 5/95	
<b>Contact:</b>	Steve Brooks			
<b>Address:</b>	PO Box 998 St. Joseph MO 64502			
<b>Phone:</b>	816-387-6258			
<b>104(e) Response Comments:</b> 104(e) response identified wastes sent to PCB on manifests 1167 and 1172. Facility files for these 2 manifests were not maintained with St. Joseph's file. Probably should check with ETI's file.				
<b>Warning Letter Comments:</b>				
Prepared by Dynamac Corporation				
Comment.DBF/J 1/21/97				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**104(e) LETTER INFO**

**WARNING LETTER INFO**

**Facility:** St. Joseph's Hospital  
**Other Name:**  
**EPA Assigned ID #:** 34025

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 9/ 5/95  
**Date of Letter** 8/31/95

**Contact:** Robert Toland II, Esq.  
**Address:** 1800 One Liberty Place  
Philadelphia PA 19103-7395  
**Phone:** 215-864-7000

**104(e) Response Comments:** Unable to locate PCB facility file for HWM #2741

**Warning Letter Comments:**

**Facility:** St. Mary's Hospital  
**Other Name:**  
**EPA Assigned ID #:** 34075

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**Contact:**  
**Address:** 1216 Second Street  
Rochester MN 55902  
**Phone:**

**104(e) Response Comments:** No returned mail, no green card, no response. Equipment information taken from PCB facility file.

**Warning Letter Comments:**

**Facility:** St. Mary's Medical Center  
**Other Name:**  
**EPA Assigned ID #:** 34100

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility**  
**Date Response Received by EPA** 10/ 6/95  
**Date of Letter** 10/ 5/95

**Contact:** Judith Kleine  
**Address:** 1000 S. Lake Park Ave  
Hobart IN 46342  
**Phone:**

**104(e) Response Comments:** Generator has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.

**Warning Letter Comments:**



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO	
Facility:	St. Paul Company	Date Sent to Facility	8/ 4/95	5/21/96
Other Name:		Date Received by Facility	8/ 8/95	5/31/96
EPA Assigned ID #:	34125	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	S. 385 Washington			
	St. Paul			
	MN 55102			
Phone:				
104(e) Response Comments:	<i>Response received 10/3/96, dated 10/2/96</i>			
Warning Letter Comments:	<del>No response received.</del> Equipment information taken from PCB facility file.			

Facility:	St. Paul Post Office	Date Sent to Facility	8/ 4/95	5/21/96
Other Name:		Date Received by Facility	8/ 9/95	5/31/96
EPA Assigned ID #:	34150	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	180 E. Kellogg			
	St. Paul			
	MN 55101			
Phone:				
104(e) Response Comments:				
Warning Letter Comments:	No response received. Equipment information taken from PCB facility file.			

Facility:	St. Peter, City of	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 6/95	
EPA Assigned ID #:	33525	Date Response Received by EPA	9/25/95	
		Date of Letter	9/21/95	
Contact:	Lewis G. Giesking			
Address:	405 W. St. Julien Street			
	St. Peter			
	MN 56082			
Phone:	507-931-4840			
104(e) Response Comments:	Unable to locate facility file. Information taken from 104(e) only.			
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO	
Facility:	St. Rose Convent	Date Sent to Facility	8/ 4/95	5/21/96
Other Name:		Date Received by Facility	8/ 7/95	5/23/96
EPA Assigned ID #:	34325	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	912 Market			
	LaCrosse			
	WI 54601			
Phone:				
104(e) Response Comments:				
Warning Letter Comments: No response received. Equipment information taken from PCB facility file.				
Facility:	Steel Warehouse Company, Inc.	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	33675	Date Response Received by EPA	9/18/95	
		Date of Letter	9/12/95	
Contact:	Gerald F. Lerman			
Address:	2722 W. Tucker Dr., P.O. Bo			
	South Bend			
	IN 46624			
Phone:	219-236-5100			
104(e) Response Comments: Generator has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.				
Warning Letter Comments:				
Facility:	Stoughton, City of	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	15450	Date Response Received by EPA	10/ 5/95	
		Date of Letter	10/ 2/95	
Contact:	Michael Skibinski, Attorne			
Address:	384 E. Main St., PO Box 90			
	Stoughton			
	WI 53589			
Phone:	608-873-6677			
104(e) Response Comments: In the 104(e) response there is no response to question #5, however, several responses refer to #5.				
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	Strangeland Electric Cooperative	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	33725	<b>Date Response Received by EPA</b>	9/11/95	
		<b>Date of Letter</b>	9/ 6/95	
<b>Contact:</b>	Larry Strangeland			
<b>Address:</b>	1330 Chestnut Dawson MN 56232			
<b>Phone:</b>	612-769-2711			
<b>104(e) Response Comments:</b>	Owner of company died in 1993 and the company was closed. Owner's son (Mr. Strangeland) has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.			
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Stuntz Cooperative	<b>Date Sent to Facility</b>	8/ 4/95	5/21/96
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/10/95	5/23/96
<b>EPA Assigned ID #:</b>	33775	<b>Date Response Received by EPA</b>		6/10/96
		<b>Date of Letter</b>		6/ 4/96
<b>Contact:</b>	Arvid Nasi			
<b>Address:</b>	2012 First Avenue Hibbing MN 55746			
<b>Phone:</b>	218-262-3813			
<b>104(e) Response Comments:</b>				
<b>Warning Letter Comments:</b>	Response states that Stuntz was sold to Minnesota Power and has been out of existence for several years.			
<b>Facility:</b>	Sturgis, City of	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95	
<b>EPA Assigned ID #:</b>	15500	<b>Date Response Received by EPA</b>	9/ 8/95	
		<b>Date of Letter</b>	9/ 6/95	
<b>Contact:</b>	Jerome R. Kisscorni			
<b>Address:</b>	P.O. Box 280 Sturgis MI 49091			
<b>Phone:</b>	616-651-2321			
<b>104(e) Response Comments:</b>	PCB concentration for oil received on HWM #0402 is 3 dr=665ppm and 2 dr=<50 ppm. Combined response with Sturgess Municipal Electric (33800).			
<b>Warning Letter Comments:</b>				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
<b>Facility:</b>	Sundstrand Corporation	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>	(Sauer Sundstrand)	<b>Date Received by Facility</b>		
<b>EPA Assigned ID #:</b>	34475	<b>Date Response Received by EPA</b>	9/ 8/95	
		<b>Date of Letter</b>	9/ 7/95	
<b>Contact:</b>	Victoria M. Haines			
<b>Address:</b>	4949 Harrison Avenue			
	Rockford IL 61125			
<b>Phone:</b>	815-226-6000			
<b>104(e) Response Comments:</b> Response includes information for Sundstrand Aviation				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Sweetwater Electric System	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/10/95	
<b>EPA Assigned ID #:</b>	34550	<b>Date Response Received by EPA</b>	9/ 8/95	
		<b>Date of Letter</b>	9/ 7/95	
<b>Contact:</b>	Frederick Hitchcock			
<b>Address:</b>	101 Oak Street			
	Sweetwater TN 27874			
<b>Phone:</b>	615-265-2000			
<b>104(e) Response Comments:</b> Generator has no knowledge or information regarding shipments made to PCB. Information taken from PCB facility file.				
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	TRW Inc.	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>		<b>Date Received by Facility</b>		
<b>EPA Assigned ID #:</b>	35600	<b>Date Response Received by EPA</b>	9/28/95	
		<b>Date of Letter</b>	9/25/95	
<b>Contact:</b>	James Mulhern			
<b>Address:</b>	1900 Richmond Road			
	Cleveland OH 44124			
<b>Phone:</b>				
<b>104(e) Response Comments:</b> Responses were received from TRW & new owner, PCC Airfoils. Combined response with TRW Ross Gear Division.				
<b>Warning Letter Comments:</b>				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** Target Products Division Feder  
**Other Name:**  
**EPA Assigned ID #:** 34675

**Contact:** James McMenemy Q.C  
**Address:** 4320-4330 Clary Blv  
Kansas City MO 64130  
**Phone:**

**104(e) Response Comments:**

**Warning Letter Comments:** Combined response with Federal Mogul (19825). Warning letter sent in error.

---

**104(e) LETTER INFO**

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

8/ 4/95  
8/ 7/95

---

**WARNING LETTER INFO**

5/21/96  
5/22/96  
5/29/96  
5/28/96

---

**Facility:** Tecumseh Products  
**Other Name:**  
**EPA Assigned ID #:** 34725

**Contact:**  
**Address:** 333 Joseph Street  
Marion OH 43302  
**Phone:**

**104(e) Response Comments:** 8/4/95 letter returned FOE. Equipment information taken from PCB facility file.

**Warning Letter Comments:**

---

**Facility:** Texaco Inc.  
**Other Name:**  
**EPA Assigned ID #:** 34775

**Contact:**  
**Address:** Box 3109  
Midland TX 79702  
**Phone:**

**104(e) Response Comments:** Texaco, Inc. responded for all locations.

**Warning Letter Comments:**

8/ 4/95  
8/ 8/95  
10/30/95  
10/26/95

m

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

---

**GENERAL INFORMATION**

**Facility:** Tilton Terrace  
**Other Name:**  
**EPA Assigned ID #:** 34975

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

---

**104(e) LETTER INFO**

8/ 4/95  
8/ 9/95

---

**WARNING LETTER INFO**

5/21/96  
5/28/96

**Contact:**

**Address:** 801 North Broom St  
Wilmington DE 19806

**Phone:****104(e) Response Comments:**

**Warning Letter Comments:** No response received. Equipment information taken from PCB facility file.

---

**Facility:** Timken Company  
**Other Name:**  
**EPA Assigned ID #:** 35000

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 9/22/95  
**Date of Letter** 9/20/95

**Contact:** Mark P. Gustafarro, Atty.  
**Address:** 1835 Dueber Avenue  
Canton OH 44706  
**Phone:**

**104(e) Response Comments:** Response includes info for both the Canton & Bucyrus, Ohio facilities. Generator has no knowledge of shipments made from the Canton facility (HWM #0924).

**Warning Letter Comments:**

---

**Facility:** Tipmont Rural Electric Members  
**Other Name:**  
**EPA Assigned ID #:** 35050

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 9/11/95  
**Date of Letter** 9/ 8/95

**Contact:** Keith Ritchey  
**Address:** U.S. Highway 231 South, P.  
Linden IN 47955-0020  
**Phone:** 317-339-7211

**104(e) Response Comments:** The 104(e) response shows 100 capacitors sent to PCB. Facility file shows that only 28 capacitors were received.

**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	Toms Foods	Date Sent to Facility	6/21/96	
Other Name:		Date Received by Facility	6/25/96	
EPA Assigned ID #:	35125	Date Response Received by EPA	7/15/96	
		Date of Letter	7/10/96	
Contact:	Woodson P. Marshall			
Address:	900 8th Street			
	Columbus GA 31994			
Phone:	706-323-2721			
104(e) Response Comments: 8/4/95 letter returned FOE. Generator provided information regarding equipment sent to ENSCO, Inc. Information taken from PCB facility file.				
Warning Letter Comments:				
Facility:	Tosoh SMD, Inc.	Date Sent to Facility	8/ 4/95	
Other Name:	(Varian Specialty Metals)	Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	36525	Date Response Received by EPA	4/11/95	
		Date of Letter	4/ 8/95	
Contact:	Conrad E. Fuchs			
Address:	3600 Gantz Road			
	Grove City OH 43123-1895			
Phone:	614-875-7912			
104(e) Response Comments: Generator has no knowledge or documents pertaining to shipments sent to PCB. Info taken from PCB facility file. Response has also been received from Varian Dated 3/25/96.				
Warning Letter Comments:				
Facility:	Tredyffrin Easttown School District	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility		
EPA Assigned ID #:	35250	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	1st and Bridge Aven			
	Berwyn PA 19312			
Phone:				
104(e) Response Comments: No returned mail, no signed green card, no response. Equipment information taken from PCB facility file.				
Warning Letter Comments:				

***PCB Treatment, Inc. General Information***  
***Review of Facilities Requiring Follow-up and Warning Letters***

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Trempealeau Electric Cooperative	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	35275	<b>Date Response Received by EPA</b>	9/11/95
		<b>Date of Letter</b>	9/ 6/95
<b>Contact:</b>	David R. Oelkers		
<b>Address:</b>	Box 277		
	Arcadia WI 54612		
<b>Phone:</b>	608-323-3381		
<b>104(e) Response Comments:</b> Information regarding HWM #2485 is included with Dairyland Coop. According to generator, HWM #1088 is also part of the Dairyland response, however, we are unable to locate any PCB files for this HWM.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Trinity Environmental Technologies, Inc.	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(Trinity Chemical Company)	<b>Date Received by Facility</b>	6/21/96
<b>EPA Assigned ID #:</b>	35400	<b>Date Response Received by EPA</b>	7/ 8/96
		<b>Date of Letter</b>	7/31/96
<b>Contact:</b>	Robert Forbes, Jr.		7/29/96
<b>Address:</b>	62 East First Street		
	Mound Valley KS 67354		
<b>Phone:</b>	316-328-3222		
<b>104(e) Response Comments:</b> Original 104(e) information request was sent to incorrect address. Letter was resent on 6/21/96			
<b>Warning Letter Comments:</b> Unable to locate facility file for HWM 8427P, 8456P, 8457P, 8458P, 8459P, 8460P, 8461P, 8462P. Information for these HWM was taken from the 104(e) response			



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

<b>GENERAL INFORMATION</b>		<b>104(e) LETTER INFO</b>	<b>WARNING LETTER INFO</b>
<b>Facility:</b>	Troy Utilities	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(Troy Municipal Utilities)	<b>Date Received by Facility</b>	8/ 8/95
<b>EPA Assigned ID #:</b>	35550	<b>Date Response Received by EPA</b>	6/10/96
		<b>Date of Letter</b>	6/ 6/96
<b>Contact:</b>	Michael Hagedorn		
<b>Address:</b>	419 Main Street		
	Tell City IN 47586		
<b>Phone:</b>	812-547-7907		
<b>104(e) Response Comments:</b>			
<b>Warning Letter Comments:</b> Generator was unable to locate any documents pertaining to shipments made to PCB. Information taken from PCB facility file.			
<b>Facility:</b>	Twin Valleys Public Power District	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95
<b>EPA Assigned ID #:</b>	35675	<b>Date Response Received by EPA</b>	9/ 5/95
		<b>Date of Letter</b>	8/31/95
<b>Contact:</b>	Micheal L. Langley		
<b>Address:</b>	Box 160		
	Cambridge NE 69022		
<b>Phone:</b>	308-697-3315		
<b>104(e) Response Comments:</b> Unable to locate PCB facility file for HWM #0069. Information taken from 104(e) response.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	UIS Company	<b>Date Sent to Facility</b>	6/21/96
<b>Other Name:</b>		<b>Date Received by Facility</b>	6/22/96
<b>EPA Assigned ID #:</b>	35750	<b>Date Response Received by EPA</b>	
		<b>Date of Letter</b>	
<b>Contact:</b>			
<b>Address:</b>	PO Box 104		
	Lee's Summit MO 64063		
<b>Phone:</b>			
<b>104(e) Response Comments:</b> 8/4/95 letter returned "attempted not known." No response received. Equipment information taken from PCB facility file.			
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	US Diamond Wheel	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	36425	Date Response Received by EPA	8/31/95
		Date of Letter	8/29/95
Contact:	West Lindquist		
Address:	400 N. Highland Ave		
	Aurora IL 60506		
Phone:			
104(e) Response Comments: Generator has no knowledge or documents pertaining to shipments made to PCB. Unable to locate any PCB files for this facility.			
Warning Letter Comments:			
Facility:	US West Communications, Incorporated	Date Sent to Facility	8/ 4/95
Other Name:	(Northwestern Bell Telephone Co.)	Date Received by Facility	8/ 7/95
EPA Assigned ID #:	28950	Date Response Received by EPA	9/27/95
		Date of Letter	9/26/95
Contact:	Jarvis W. Seccombe		
Address:	7800 E. Orchard Rd., Ste. 48		
	Englewood CO 80111		
Phone:	303-796-6055		
104(e) Response Comments: Generator has no knowledge or documents pertaining to shipments sent to PCB. Information taken from PCB facility file.			
Warning Letter Comments:			
Facility:	Union Electric Membership Corporation	Date Sent to Facility	8/ 4/95
Other Name:	(Union Electric)	Date Received by Facility	
EPA Assigned ID #:	35775	Date Response Received by EPA	8/28/95
		Date of Letter	8/24/95
Contact:	Thomas Slusher		
Address:	PO Box 5014		
	Monroe NC 28111-5014		
Phone:	800-922-6840		
104(e) Response Comments: Generator has no knowledge or documents pertaining to shipments made to PCB. Contractor was unable to locate any PCB files for this facility.			
No information has been entered into the equipment database.			
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	Union Underwear Company Incorporated	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	36100	Date Response Received by EPA	3/26/95	
		Date of Letter	3/25/95	
Contact:	Daniel Shuler, VP			
Address:	PO Box 90015			
	Bowling Green KY 42102-9015			
Phone:	502-781-6400			
104(e) Response Comments: Unable to locate PCB facility files for HWM #2575, 2573, 2572, 0931. Information taken from 104(e) response only.				
Warning Letter Comments:				
Facility:	Union Yarn Mills	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility		
EPA Assigned ID #:	36125	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	First Street			
	Jacksonville AL 36265			
Phone:				
104(e) Response Comments: No returned green card, no returned mail, no response. Equipment information taken from PCB facility file.				
Warning Letter Comments:				
Facility:	United Properties	Date Sent to Facility	5/21/96	
Other Name:		Date Received by Facility	5/24/96	
EPA Assigned ID #:	36200	Date Response Received by EPA		
		Date of Letter		
Contact:				
Address:	3500 W. 80th St.			
	Minneapolis MN 55431			
Phone:				
104(e) Response Comments: 8/4/95 letter returned FOE. No response received. Equipment information taken from PCB facility file.				
Warning Letter Comments:				

***PCB Treatment, Inc. General Information***  
***Review of Facilities Requiring Follow-up and Warning Letters***

<b>GENERAL INFORMATION</b>		<b>104(e) LETTER INFO</b>	<b>WARNING LETTER INFO</b>
<b>Facility:</b>	United Rural Electric Membership Corporat	<b>Date Sent to Facility</b>	6/21/96
<b>Other Name:</b>	(United REMC)	<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	36225	<b>Date Response Received by EPA</b>	7/12/96
		<b>Date of Letter</b>	7/ 9/96
<b>Contact:</b>	Randy Laugle		
<b>Address:</b>	Box 605		
	Markle IN 46770-0605		
<b>Phone:</b>	219-758-3155		
<b>104(e) Response Comments:</b> 8/4/95 letter returned FOE.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	United States Testing Company	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95
<b>EPA Assigned ID #:</b>	36250	<b>Date Response Received by EPA</b>	9/11/95
		<b>Date of Letter</b>	9/ 6/95
<b>Contact:</b>	R. Kennedy Bridwell, Atty		
<b>Address:</b>	9 Campus Drive		
	Parsippany NJ 70754-3672		
<b>Phone:</b>	201-993-3672		
<b>104(e) Response Comments:</b> Generator has no knowledge or documents pertaining to shipments made to PCB. Info taken from PCB facility file.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	University of South Dakota	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	36350	<b>Date Response Received by EPA</b>	10/10/95
		<b>Date of Letter</b>	10/ 6/95
<b>Contact:</b>	Kenneth L. Schmidt		
<b>Address:</b>	414 East Clark		
	Vermillion SD 57069-239		
<b>Phone:</b>	605-677-5341		
<b>104(e) Response Comments:</b> Unable to locate PCB facility files for HWM #3549 & 4059.			
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Upshur Rural Electric	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	36400	<b>Date Response Received by EPA</b>	8/28/97
<b>Contact:</b>		<b>Date of Letter</b>	8/26/97
<b>Address:</b>	c/o Campos Engineer Dallas TX 75240		
<b>Phone:</b>			
<b>104(e) Response Comments:</b>	8/4/95 letter returned FOE. Equipment information taken from PCB facility file.		
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Valley Electric Association	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(Valley Co. Electric Coop)	<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	36500	<b>Date Response Received by EPA</b>	8/25/95
<b>Contact:</b>	Brent Crowther	<b>Date of Letter</b>	8/21/95
<b>Address:</b>	800 E. Highway 372, P.O. B Pahrump NV 89041		
<b>Phone:</b>	702-727-5312		
<b>104(e) Response Comments:</b>	Unable to locate PCB facility file for HWM #0686.		
<b>Warning Letter Comments:</b>	Unable to locate PCB facility file for HWM #0686. Information taken from PCB facility file.		
<b>Facility:</b>	Vera Water & Power	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	36575	<b>Date Response Received by EPA</b>	11/21/95
<b>Contact:</b>	Kevin Wells	<b>Date of Letter</b>	11/15/95
<b>Address:</b>	601 N. Evergreen, P.O. Box Veradale WA 99037-0630		5/21/96
<b>Phone:</b>	509-924-3800		5/23/96
<b>104(e) Response Comments:</b>	Combined response with Vera Irrigation District No. 15. Unable to locate facility file for HWM #0690 for this facility.		
<b>Warning Letter Comments:</b>	Warning letter sent in error.		

***PCB Treatment, Inc. General Information***  
***Review of Facilities Requiring Follow-up and Warning Letters***

GENERAL INFORMATION		104(e) LETTER INFO		WARNING LETTER INFO
Facility:	Vermillion City Light & Power	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	36600	Date Response Received by EPA	9/ 5/95	
		Date of Letter	8/29/95	
Contact:	Bruce Brunick			
Address:	25 Center Street Vermillion SD 57069			
Phone:	605-677-7074			
104(e) Response Comments:	Combined response with City of Vermillion. Unable to locate PCB facility file for HWM #0906.			
Warning Letter Comments:	Unable to locate PCB file for HWM #0906. Information taken from 104(e) response.			
Facility:	Villisca Municipal Power Plant	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	36950	Date Response Received by EPA	9/ 8/95	
		Date of Letter	9/ 6/95	
Contact:	David Hunter			
Address:	318 South 3rd Avenue Villisca IA 50864			
Phone:	712-826-2004			
104(e) Response Comments:	Unable to locate any PCB files for this facility. All information taken from the 104(e) response.			
Warning Letter Comments:				
Facility:	W & M Manufacturing	Date Sent to Facility	8/ 4/95	
Other Name:		Date Received by Facility	8/ 7/95	
EPA Assigned ID #:	36975	Date Response Received by EPA	9/ 5/95	
		Date of Letter	8/24/95	
Contact:	Robert JcCabe			
Address:	PO Box 1088 Portland IN 47371			
Phone:	219-726-9800			
104(e) Response Comments:	Company records were burned in a fire. Information was taken from the "Session file."			
Warning Letter Comments:				

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	WAYL Radio	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	37300	Date Response Received by EPA	
		Date of Letter	
Contact:			
Address:	2100 Cliff Road		
	Egan MN 55122		
Phone:			
104(e) Response Comments: No response received. Unable to locate PCB facility file. Equipment information taken from "Session" file.			
Warning Letter Comments:			
Facility:	Warner Lambert	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 8/95
EPA Assigned ID #:	37075	Date Response Received by EPA	10/10/95
		Date of Letter	10/ 5/95
Contact:	Michael J. Myers		
Address:	201 Tabor Road		
	Morris Plains NJ 07950		
Phone:	202-861-1598		
104(e) Response Comments: Generator has no knowledge or documents pertaining to shipments sent to PCB. Information taken from PCB facility file.			
Warning Letter Comments:			
Facility:	Warren, City of	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	15575	Date Response Received by EPA	5/21/96
		Date of Letter	5/24/96
Contact:	David Berg		
Address:	126 W. Johnson Ave		
	Warren MN 56762		
Phone:	None		
104(e) Response Comments:			
Warning Letter Comments: Response received has no EPA received date stamped, there is no date on the response, and no envelope is included.			

***PCB Treatment, Inc. General Information***  
***Review of Facilities Requiring Follow-up and Warning Letters***

<b>GENERAL INFORMATION</b>		<b>104(e) LETTER INFO</b>		<b>WARNING LETTER INFO</b>
<b>Facility:</b>	Waterloo Light & Power	<b>Date Sent to Facility</b>	8/ 4/95	5/21/96
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 7/95	5/23/96
<b>EPA Assigned ID #:</b>	37200	<b>Date Response Received by EPA</b>		
		<b>Date of Letter</b>		
<b>Contact:</b>				
<b>Address:</b>	104 W. 4th Street Waterloo IL 62298			
<b>Phone:</b>				
<b>104(e) Response Comments:</b>	Same facility as Waterloo Municipal Light & Power.			
<b>Warning Letter Comments:</b>	No response received. Equipment information taken from PCB facility file.			
<b>Facility:</b>	Watertown Municipal Utilities Department	<b>Date Sent to Facility</b>	8/ 4/95	
<b>Other Name:</b>	(Municipal Utilities Dept.)	<b>Date Received by Facility</b>	8/ 7/95	
<b>EPA Assigned ID #:</b>	27475	<b>Date Response Received by EPA</b>	9/ 7/95	
		<b>Date of Letter</b>		
<b>Contact:</b>				
<b>Address:</b>	901 4th Avenue SW Watertown SD 57201			
<b>Phone:</b>				
<b>104(e) Response Comments:</b>	Generator sent documents but no sheet which answered questions. Unable to locate PCB facility file for HWM #0306.			
<b>Warning Letter Comments:</b>				
<b>Facility:</b>	Wayne Corporation	<b>Date Sent to Facility</b>	6/21/96	
<b>Other Name:</b>		<b>Date Received by Facility</b>	6/24/96	
<b>EPA Assigned ID #:</b>	37325	<b>Date Response Received by EPA</b>	7/ 2/96	
		<b>Date of Letter</b>	6/25/96	
<b>Contact:</b>	Wayne Nichols			
<b>Address:</b>	PO Box 611 Mattapoisett MA 02739			
<b>Phone:</b>	508-993-7210			
<b>104(e) Response Comments:</b>	8/4/95 letter returned FOE. Followup letter was sent to Mattapoisett, MA. Response indicates that this is not the same company. Information taken from PCB facility file.			
<b>Warning Letter Comments:</b>				



**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	Wayne Farms Division of Continental Grai	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(Wayne Poultry Division of Continental Gra	<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	37375	<b>Date Response Received by EPA</b>	6/21/96
		<b>Date of Letter</b>	6/19/96
<b>Contact:</b>	Joey Daniel		
<b>Address:</b>	3400 Jessee Jewell Parkway, Gainesville GA 30501		
<b>Phone:</b>	770-538-2120		
<b>104(e) Response Comments:</b> Unable to locate any PCB facility files for this facility. The HWM # provided with the 104(e) response is illegible.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Weed Heights Development	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	37500	<b>Date Response Received by EPA</b>	10/19/95
		<b>Date of Letter</b>	
<b>Contact:</b>	Don and Joy Tibbals		
<b>Address:</b>	2 Austin Drive Yerington NV 89447		
<b>Phone:</b>			
<b>104(e) Response Comments:</b> Generator has no knowledge or information regarding equipment sent to PCB. Information taken from PCB facility file.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	WestPlains Energy	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	(Southern Colorado Power)	<b>Date Received by Facility</b>	8/ 7/95
<b>EPA Assigned ID #:</b>	33100	<b>Date Response Received by EPA</b>	
		<b>Date of Letter</b>	9/20/95
<b>Contact:</b>	Robert Beck		
<b>Address:</b>	Box 75 Pueblo CO 81002		
<b>Phone:</b>	816-737-7538		
<b>104(e) Response Comments:</b> Future correspondence to Robert Beck, Missouri Public Service, 10700 E. 350 Highway, KC, MO 64138			
<b>Warning Letter Comments:</b>			

***PCB Treatment, Inc. General Information***  
***Review of Facilities Requiring Follow-up and Warning Letters***

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
<b>Facility:</b>	WestPlains Energy	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>	Centel Western Power	<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	13900	<b>Date Response Received by EPA</b>	10/ 6/95
		<b>Date of Letter</b>	10/ 6/95
<b>Contact:</b>	Robert Beck		
<b>Address:</b>	10700 E. 350 Hwy. Kansas City MO 64138		
<b>Phone:</b>	816-737-7538		
<b>104(e) Response Comments:</b> 2nd address to respond is: 1409 SE 7th Court, (816)524-5980			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Western Farmers Electric Cooperation	<b>Date Sent to Facility</b>	8/ 4/95
<b>Other Name:</b>		<b>Date Received by Facility</b>	8/ 8/95
<b>EPA Assigned ID #:</b>	37550	<b>Date Response Received by EPA</b>	8/18/95
		<b>Date of Letter</b>	8/ 8/95
<b>Contact:</b>	Don Sissan		
<b>Address:</b>	701 N.E. 7th, Box 429 Anadarko OK 73005		
<b>Phone:</b>	405-247-3351		
<b>104(e) Response Comments:</b> Generator has no knowledge or information pertaining to equipment sent to PCB. Information taken from PCB facility file.			
<b>Warning Letter Comments:</b>			
<b>Facility:</b>	Westvaco Corp.-Bleached Board	<b>Date Sent to Facility</b>	
<b>Other Name:</b>		<b>Date Received by Facility</b>	
<b>EPA Assigned ID #:</b>	37675	<b>Date Response Received by EPA</b>	
		<b>Date of Letter</b>	
<b>Contact:</b>			
<b>Address:</b>	Covington VA 24426		
<b>Phone:</b>			
<b>104(e) Response Comments:</b> Combined response with Westvaco Corporation (37650).			
<b>Warning Letter Comments:</b>			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Westvaco Corporation	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	37650	Date Response Received by EPA	10/10/95
		Date of Letter	10/ 9/95
Contact:	Robert Dickinson		
Address:	299 Park Avenue		
	New York NY 10171		
Phone:	212-688-5000		
104(e) Response Comments: Unable to locate PCB facility files for HWM #1972, 1971, 1962A, 1963A, 1964A, 2384. Information taken from 104(e) response only.			
Warning Letter Comments:			
Facility:	Whetstone Valley Electric Cooperative	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	37775	Date Response Received by EPA	9/ 7/95
		Date of Letter	9/ 5/95
Contact:	Dave Snaza		
Address:	Box 512		
	Milbank SD 57252		
Phone:	605-432-5331		
104(e) Response Comments: Unable to locate PCB facility files for HWM #2393 and 3683. Information taken from 104(e) response. Response identified a shipment on 8/20/83, however no additional information was provided.			
Warning Letter Comments:			
Facility:	Whirlpool Corporation	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 8/95
EPA Assigned ID #:	37800	Date Response Received by EPA	8/14/95
		Date of Letter	8/10/95
Contact:	John Stansbury		
Address:	2000 M-63 (Mail Drop 2200)		
	Benton Harbor MI 49022		
Phone:	616-923-5014		
104(e) Response Comments: Whirlpool Corporation is responding for all Whirlpools.			
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Whitley County REMC	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	
EPA Assigned ID #:	37900	Date Response Received by EPA	
		Date of Letter	
Contact:	St. Stocker Genera		
Address:	Box 171		
	Columbia Ci IN 46725		
Phone:			
104(e) Response Comments:	No returned mail, no signed green card, no response. Equipment information taken from PCB facility file.		
Warning Letter Comments:			
Facility:	Wilkes-Barre Housing Authority	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	37925	Date Response Received by EPA	9/11/95
		Date of Letter	9/ 1/95
Contact:	Leon F. Case		
Address:	50 Lincoln Plaza		
	Wilkes-Barre PA 18702-5198		
Phone:	717-825-6657		
104(e) Response Comments:	Response did not include information for HWM #2787. Information taken from PCB facility file.		
Warning Letter Comments:			
Facility:	William B. Wood Safety Officer	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	37950	Date Response Received by EPA	
		Date of Letter	
Contact:	Robert E. Stuart		
Address:	East Wing City Hall		
	Norfolk VA 23510		
Phone:			
104(e) Response Comments:	No response received. Equipment information taken from PCB facility file.		
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

GENERAL INFORMATION		104(e) LETTER INFO	WARNING LETTER INFO
Facility:	Wilmar Municipal Utilities	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	38050	Date Response Received by EPA	8/14/95
		Date of Letter	8/10/95
Contact:	John L. Brinkman		
Address:	PO Box 937		
	Willmar MN 56201		
Phone:	612-235-4422		
104(e) Response Comments: HWM #0125 has 2 Certificates of Destruction: 12/2/83 and 3/7/84.			
Warning Letter Comments:			
Facility:	Wilson Foods	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	38075	Date Response Received by EPA	
		Date of Letter	5/21/96
Contact:			
Address:	E. Main Street		
	Albert Lea MN 56007		
Phone:			
104(e) Response Comments:			
Warning Letter Comments: Warning letter returned "Refused"			
Facility:	Winona State University	Date Sent to Facility	8/ 4/95
Other Name:		Date Received by Facility	8/ 7/95
EPA Assigned ID #:	38100	Date Response Received by EPA	10/ 5/95
		Date of Letter	10/ 5/95
Contact:	Sherry A. Enzler		
Address:	1100 NCL Tower, 445 Minn		
	St. Paul MN 55101-2128		
Phone:	612-282-5705		
104(e) Response Comments: The State of Minnesota - Office of the Attorney General is responding for Winona State University.			
Warning Letter Comments:			

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Winterthur Museum and Gardens  
**Other Name:**  
**EPA Assigned ID #:** 38125

**Contact:**  
**Address:** Winterthur DE 19735  
**Phone:**

**Date Sent to Facility**  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) LETTER INFO**

8/ 4/95

**WARNING LETTER INFO**

**104(e) Response Comments:** Green card is returned but is not signed or postmarked. No returned mail, no response. Equipment information taken from PCB facility file.  
**Warning Letter Comments:**

**Facility:** Wisconsin, State of  
**Other Name:** (Wisconsin Dept. of Natural Resources)  
**EPA Assigned ID #:** 38150

**Contact:** Charles Larsen  
**Address:** PO Box 7857  
Madison WI 53707-7857  
**Phone:** 608-266-1767

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 7/95  
**Date Response Received by EPA** 9/ 8/95  
**Date of Letter** 9/ 5/95

**104(e) Response Comments:** Combines response with the University of Wisconsin - Platteville.  
**Warning Letter Comments:**

**Facility:** Witco Chemical Corporation  
**Other Name:**  
**EPA Assigned ID #:** 38200

**Contact:** James A. Nortz  
**Address:** One American Lane  
Greenwich CT 06831-2559  
**Phone:** 203-552-2820

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 9/95  
**Date Response Received by EPA**  
**Date of Letter** 5/22/95

**104(e) Response Comments:** Response includes information for Argus Chemical. Generator has no knowledge or information pertaining to shipments made to PCB. Information taken from PCB facility files.  
**Warning Letter Comments:**

**PCB Treatment, Inc. General Information**  
**Review of Facilities Requiring Follow-up and Warning Letters**

**GENERAL INFORMATION**

**Facility:** Withlacoochee River Electric  
**Other Name:**  
**EPA Assigned ID #:** 38225

**Contact:** Johnnie Byrd  
**Address:** PO Box TT  
Plant City FL 33564-9040  
**Phone:**

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility** 8/ 8/95  
**Date Response Received by EPA** 9/15/95  
**Date of Letter** 9/11/95

**104(e) LETTER INFO**

**WARNING LETTER INFO**

**104(e) Response Comments:** Unable to locate PCB facility file. Total manifest weight is 2,453 lb.  
**Warning Letter Comments:**

**Facility:** Wood County Electric Coop  
**Other Name:**  
**EPA Assigned ID #:** 38250

**Contact:** Jim Dozier  
**Address:** PO Box 398  
Quitman TX 75783  
**Phone:** 903-763-2203

**Date Sent to Facility** 6/21/96  
**Date Received by Facility** 6/25/96  
**Date Response Received by EPA** 7/29/96  
**Date of Letter** 7/26/96

**104(e) Response Comments:** 8/4/95 letter returned FOE.  
**Warning Letter Comments:**

**Facility:** Wright Co. Inc.  
**Other Name:**  
**EPA Assigned ID #:** 38325

**Contact:**  
**Address:** 206 W. 4th Street  
Monticello MN 55362  
**Phone:**

**Date Sent to Facility** 8/ 4/95  
**Date Received by Facility**  
**Date Response Received by EPA**  
**Date of Letter**

**104(e) Response Comments:** 8/4/95 letter returned REFUSED. Equipment information taken from PCB facility file.  
**Warning Letter Comments:**

m